



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 1 of 3
Date Printed: 2015/12/14
User Id: IDIR\SMROOKE
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-020	Site #:	G6-020	Road Name:	FINLAY FSR	Inspection Date:	2010/09/21
KM:	143.30	User km:	143.30	Crossing Name:	Unnamed creek	Next Inspection Date:	2016/07/09
Project File ID #:	7829	Br.	01	Forest District:	Mackenzie Natural Resource District		
Deck Type:	Concrete			Running Surface:	Not Available		
Superstructure	Steel I-beam			Abutments (Left/Right): <i>(looking downstream)</i>	Binwall		
Total Length (metres):	8.0	# Spans:	1	Span Length(s) (metres):	8		
UTM Zone:	10	UTM Easting:	421445	UTM Northing:	6199748		
Inspector Name:	Greg Honeysett			Year Superstructure Installed:	1989		
Access:							

ABUTMENTS

Bearings	Unrated	Cannot see
Binwall	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Good	
Caps or Sills	Unrated	Cannot see between Bin wall and Superstructure combined with Grader berm buildup
Fill	Good	
Hardware	Unrated	Cannot see
Piles or Posts	Unrated	Cannot see
Riprap	Poor	None on site
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left <i>(approaching structure)</i>	1	
Delineator Missing Right <i>(approaching structure)</i>	0	
Fender Condition	Good	
Road Surface	Good	

DECK

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 2 of 3
Date Printed: 2015/12/14
User Id: IDIR\SMROOKE
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-020	Site #:	G6-020	Road Name:	FINLAY FSR	Inspection Date:	2010/09/21
--------------	--------	---------	--------	------------	------------	------------------	------------

Span 1

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Poor	Blcoks need replacement
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Fair	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Good	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	5.0
	Estimated High Water Level Clearance:	0.7		

HAZARDS	High Water:	Yes	Scour:	Yes	Ice:	No	Debris:	Yes	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Suggested	Medium	\$0.00	New delineators
	2	Suggested	Medium	\$0.00	Replace curb blocks

MONITORS	#	Description
	1	Water is right up to abutments on both sides potential for scour as there is no Rip Rap on site
	2	Beaver activity upstream

GENERAL	Inspector's Comment:	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 3 of 3
Date Printed: 2015/12/14
User Id: IDIR\SMROOKE
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-020	Site #:	G6-020	Road Name:	FINLAY FSR	Inspection Date:	2010/09/21
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments					
GENERAL	Replacement Date for full log haul traffic (year):			2029	Replacement Date for light vehicle traffic (year):		
	Current Inspection Load Rating:		See footnote	Design Load GVW (tonnes):	91	Design Vehicle Config.:	L100
	Professional Inspection Required?		No	Report Status:	Accepted By Raymond Getzlaf on 4/26/2011 12:00:00AM		

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.