



BC Ministry of Forests and Range

Major Culvert Inspection Report

Page 1 of 2

Date Printed: 2015/12/14

User Id: IDIR\SMROOKE

Database: PROD

Report Id: CBR001C

File:

Structure #:	G6-021	Site #:	G6-021	Road Name:	FINLAY FSR	Inspection Date:	2013/07/09
KM:	144.20	User km:	145.20	Crossing Name:	Strandberg Creek	Next Inspection Date:	2016/07/09
Project File ID #:	7829	Br.	01	Forest District:	Mackenzie Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	5,000			Outlet Cover (mm):	5,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	35.0	Opening Height (mm):	2,200	Opening Width (mm):	2,200		
UTM Zone:	10	UTM Easting:	421121	UTM Northing:	6201693		
Inspector Name:	Knut Herzog			Year Superstructure Installed:	1987		
Access:							

APPROACHES

Alignment	Good
-----------	------

Bridge Ahead Signs Missing	0
----------------------------	---

Brushing Required	Yes
-------------------	-----

Delineator Missing Left (approaching structure)	0
--	---

Fender Condition	None
------------------	------

Road Surface	Good
--------------	------

CULVERT ELEMENT

Baffles	Not Applicable
---------	----------------

Bolted Connections	Not Applicable
--------------------	----------------

Coupled Connections	Good
---------------------	------

Coating	Good
---------	------

Embedment Materials	Not Applicable
---------------------	----------------

Fill	Good
------	------

Floor	Good
-------	------

Footing	Not Applicable
---------	----------------

Head Wall	Not Applicable
-----------	----------------

Inlet	Good
-------	------

Outlet	Good
--------	------

Overall	Good
---------	------

Riprap	Not Applicable
--------	----------------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Major Culvert Inspection Report

Page 2 of 2
Date Printed: 2015/12/14
User Id: IDIR\SMROOKE
Database: PROD
Report Id: CBR001C
File:

Structure #:	G6-021	Site #:	G6-021	Road Name:	FINLAY FSR	Inspection Date:	2013/07/09			
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.2	Estimated Present Water Level Width:	1.1						
	Estimated High Water Level Clearance:	1.0								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	Good Culvert								
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments								
GENERAL	Replacement Date for full log haul traffic (year):	2021	Replacement Date for light vehicle traffic (year):							
	Current Inspection Load Rating:	91	Design Load GVW (tonnes):	91	Design Vehicle Config.:					
	Professional Inspection Required?	No	Report Status:	Accepted By Jason Olmsted on 12/12/2013 12:00:00AM						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.