



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 1 of 3
Date Printed: 2015/12/14
User Id: IDIR\SMROOKE
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-024	Site #:	G6-024	Road Name:	FINLAY FSR	Inspection Date:	2013/08/13
KM:	159.70	User km:	159.90	Crossing Name:	Unnamed creek	Next Inspection Date:	2016/08/13
Project File ID #:	7829	Br.	01	Forest District:	Mackenzie Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Superstructure	Steel I-beam			Abutments (Left/Right): <small>(looking downstream)</small>	Binwall		
Total Length (metres):	9.0	# Spans:	1	Span Length(s) (metres):	9		
UTM Zone:	10	UTM Easting:	414303	UTM Northing:	6211363		
Inspector Name:	Knut Herzog			Year Superstructure Installed:	1989		
Access:							

ABUTMENTS

Bearings	Good	needs cleaning
Binwall	Good	
Bracing	Not Applicable	
Ballast Wall	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	Needs cleaning
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Not Applicable	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	Yes	
Delineator Missing Left <small>(approaching structure)</small>	2	
Delineator Missing Right <small>(approaching structure)</small>	1	
Fender Condition	Good	
Road Surface	Good	

DECK

Span 1

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 2 of 3
Date Printed: 2015/12/14
User Id: IDIR\SMROOKE
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-024	Site #:	G6-024	Road Name:	FINLAY FSR	Inspection Date:	2013/08/13
--------------	--------	---------	--------	------------	------------	------------------	------------

Concrete Deck	Good	
Curb Rail/Blocks/Posts	Poor	Needs replacement
Deck Joints	Good	
Grout Pockets	Good	
Hardware	Not Applicable	
Hand Rails/Walkouts	Not Applicable	
Overall Deck Condition	Good	

SUPERSTRUCTURE

Span 1

Bracing	Good	
Diaphragms	Good	
Girders	Good	
Hardware	Not Applicable	
Under Trussing	Not Applicable	

CHANNEL	Estimated Present Water Level Depth:	0.3	Estimated Present Water Level Width:	1.3
	Estimated High Water Level Clearance:	2.0		

HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									

REPAIRS	#	Status	Priority	Estimate	Description
	1	Suggested	High	\$5,000.00	Bull rails

MONITORS	#	Description

GENERAL	Inspector's Comment:	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 3 of 3
Date Printed: 2015/12/14
User Id: IDIR\SMROOKE
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-024	Site #:	G6-024	Road Name:	FINLAY FSR	Inspection Date:	2013/08/13
GENERAL	PEng's Comment:	Refer to Inspection Comments for historical PEng Comments					
GENERAL	Replacement Date for full log haul traffic (year):			2021	Replacement Date for light vehicle traffic (year):		
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status: Accepted By Jason Olmsted on 12/12/2013 12:00:00AM			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.