



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 1 of 3
Date Printed: 2015/12/14
User Id: IDIR\SMROOKE
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-042	Site #:	G6-042	Road Name:	FINLAY FSR	Inspection Date:	2013/07/09
KM:	147.00	User km:	147.00	Crossing Name:	UNK	Next Inspection Date:	2016/07/09
Project File ID #:	7829	Br.	01	Forest District:	Mackenzie Natural Resource District		
Deck Type:	Concrete			Running Surface:	Concrete		
Superstructure	Steel Box Beam			Abutments (Left/Right): (looking downstream)	Concrete Precast		
Total Length (metres):	15.2	# Spans:	1	Span Length(s) (metres):	15.2		
UTM Zone:	10	UTM Easting:	421160	UTM Northing:	6203584		
Inspector Name:	Knut Herzog			Year Superstructure Installed:	2007		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Concrete Precast	Good	
Corrosion Protection	Not Applicable	
Caps or Sills	Good	
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	1	
Brushing Required	No	
Delineator Missing Left (approaching structure)	1	
Delineator Missing Right (approaching structure)	2	
Fender Condition	Good	
Road Surface	Good	

DECK

Span 1

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 2 of 3

Date Printed: 2015/12/14

User Id: IDIR\SMROOKE

Database: PROD

Report Id: CBR001A

File:

Structure #:	G6-042	Site #:	G6-042	Road Name:	FINLAY FSR	Inspection Date:	2013/07/09			
Concrete Deck	Good									
Curb Rail/Blocks/Posts	Good	1 riser bolt broken HC side on Up stream side								
Deck Joints	Good									
Grout Pockets	Good									
Hardware	Not Applicable									
Hand Rails/Walkouts	Not Applicable									
Overall Deck Condition	Good									
Running Surface	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Not Applicable									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.3		Estimated Present Water Level Width:		1.4			
	Estimated High Water Level Clearance:		2.0							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 3 of 3
Date Printed: 2015/12/14
User Id: IDIR\SMROOKE
Database: PROD
Report Id: CBR001A
File:

Structure #:	G6-042	Site #:	G6-042	Road Name:	FINLAY FSR	Inspection Date:	2013/07/09
GENERAL	PEng's Comment:						
GENERAL	Replacement Date for full log haul traffic (year):			2057	Replacement Date for light vehicle traffic (year):		
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.: L100
	Professional Inspection Required?		No	Report Status: Accepted By Jason Olmsted on 6/27/2014 2:17:09PM			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.