



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 1 of 3
Date Printed: 2016/01/27
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001B
File:

Structure #:	G6-990	Site #:	G6-357	Road Name:	THUT 14000	Inspection Date:	2015/09/26
KM:	854.50	User km:		Crossing Name:	UNK	Next Inspection Date:	2017/09/26
Project File ID #:	10628	Br.	01	Forest District:	Mackenzie Natural Resource District		
Deck Type:	Timber - Untreated			Running Surface:	Timber Planks		
Superstructure	Steel I-beam			Abutments (Left/Right): (looking downstream)	Sill -Temporary Materials		
Total Length (metres):	9.1	# Spans:	1	Span Length(s) (metres):	1		
UTM Zone:	10	UTM Easting:	430448	UTM Northing:	6125599		
Inspector Name:	Edward Folk, P.Eng.			Year Superstructure Installed:	2009		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Fair	
Corrosion Protection	Not Applicable	
Caps or Sills	Fair	very moist
Fill	Fair	
Hardware	Fair	
Piles or Posts	Not Applicable	
Riprap	Fair	
Wing Wall	Fair	

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	on site but down
Delineator Missing Right (approaching structure)	0	on site but down
Fender Condition	Fair	starting to rot
Road Surface	Fair	

DECK


Span 1

Curb Rail/Blocks/Posts	Poor	rotten
------------------------	------	--------

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.





BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 2 of 3
Date Printed: 2016/01/27
User Id: IDIR\JOLMSTED
Database: PROD
Report Id: CBR001B
File:

Structure #:	G6-990	Site #:	G6-357	Road Name:	THUT 14000	Inspection Date:	2015/09/26			
Deck to Girder Bolts	Fair									
Hardware	Fair									
Hand Rails/Walkouts	Not Applicable									
Nails	Fair									
Overall Deck Condition	Fair									
Running Planks	Poor	rotten sections and holes								
Sub Deck	Unrated	no subdeck								
Ties	Fair									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Not Applicable									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		2.0		Estimated Present Water Level Width:		3.4			
	Estimated High Water Level Clearance:		1.1							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	High	\$1,200.00	replace guardrails prior to industrial use					
	2	Required	High	\$300.00	repair or replace delineators prior to industrial use					
	3	Required	High	\$2,500.00	replace deck prior to industrial use					
MONITORS	#	Description								
GENERAL	Inspector's Comment:	Sept/2015-should down rate load rating until new deck.								

Corporate Bridge Register (CBR)

Disclaimer:

1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.

2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 3 of 3
Date Printed: 2016/01/27
User Id: IDIR\JOLMSTED
Database: PROD
Report Id: CBR001B
File:

Structure #:	G6-990	Site #:	G6-357	Road Name:	THUT 14000	Inspection Date:	2015/09/26
GENERAL	PEng's Comment:	Bridge will need new deck soon. Should also see if sill logs will need replacing at the same time. The bridge could be down rated at anytime if the repairs are not completed.					
GENERAL	Replacement Date for full log haul traffic (year):			2024	Replacement Date for light vehicle traffic (year):		
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 1/27/2016 12:20:26PM	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.