



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 1 of 3
Date Printed: 2016/01/27
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001B
File:

Structure #:	G6-952	Site #:	G6-360	Road Name:	RAIN 3237	Inspection Date:	2015/09/23
KM:	2.10	User km:	2.10	Crossing Name:	Unknown	Next Inspection Date:	2017/09/23
Project File ID #:	9640	Br.	03	Forest District:	Mackenzie Natural Resource District		
Deck Type:	Timber - Untreated - Panels			Running Surface:	Timber Planks		
Superstructure	Steel I-beam			Abutments (Left/Right): (looking downstream)	Crib, Log or Untreated Timber		
Total Length (metres):	9.1	# Spans:	1	Span Length(s) (metres):	9.1		
UTM Zone:	10	UTM Easting:	428936	UTM Northing:	6098292		
Inspector Name:	Edward Folk, P.Eng.			Year Superstructure Installed:	2006		
Access:							

ABUTMENTS

Bearings	Not Applicable	
Bracing	Not Applicable	
Ballast Wall	Fair	starting to rot
Corrosion Protection	Not Applicable	
Caps or Sills	Unrated	no access under struture
Fill	Good	
Hardware	Fair	
Log/Timber Cribbs	Unrated	no crib
Piles or Posts	Not Applicable	
Riprap	Not Applicable	
Tie-backs	Not Applicable	
Wing Wall	Not Applicable	


APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	1	on site but down
Fender Condition	Fair	starting to rot
Road Surface	Poor	need grading and unplug culverts

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.





BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 2 of 3
Date Printed: 2016/01/27
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001B
File:

Structure #:	G6-952	Site #:	G6-360	Road Name:	RAIN 3237	Inspection Date:	2015/09/23
--------------	--------	---------	--------	------------	-----------	------------------	------------

DECK

Span 1

Curb Rail/Blocks/Posts	Fair	starting to show signs of rot
Deck to Girder Bolts	Fair	
Hardware	Fair	
Hand Rails/Walkouts	Not Applicable	
Nails	Fair	
Overall Deck Condition	Fair	
Running Planks	Fair	some are damaged and some are starting to rot
Sub Deck	Fair	
Ties	Fair	

SUPERSTRUCTURE

Span 1

Bracing	Unrated	no access to underneath structure
Diaphragms	Unrated	no access to underneath structure
Girders	Fair	
Hardware	Unrated	no access to underneath structure
Under Trussing	Not Applicable	

CHANNEL

Estimated Present Water Level Depth:	0.1	Estimated Present Water Level Width:	1.1
Estimated High Water Level Clearance:	0.2		

HAZARDS

High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
Comment:									

REPAIRS

#	Status	Priority	Estimate	Description

MONITORS

#	Description
1	Deck starting to rot

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Log Stringer Bridge Inspection Report

Page 3 of 3
Date Printed: 2016/01/27
User Id: IDIR\JOLMSTED
Database: PROD
Report Id: CBR001B
File:

Structure #:	G6-952	Site #:	G6-360	Road Name:	RAIN 3237	Inspection Date:	2015/09/23
GENERAL	Inspector's Comment:	sketchy access					
GENERAL	PEng's Comment:						
GENERAL	Replacement Date for full log haul traffic (year):			2021	Replacement Date for light vehicle traffic (year):		
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.:
	Professional Inspection Required?		No	Report Status:		Reviewed By Jason Olmsted on 1/27/2016 11:54:06AM	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.