





- 3 Rehab Point Treatment (RPTType)**
- Branch Berm (BB)
 - Cross Drain - Head (CD)
 - Cross Drain - Repair (CR)
 - Culvert - Clean/Repair Culvert (CC)
 - Danger Tree Treatment Required (DTA)
 - Decayed Wood (DW)
 - Dist - Clean/Repair (CD)
 - Dry Seed (DS)
 - Foot Inlet (FI)
 - Other Rehab Treatment Type
 - Pull Back (PB)
 - Shrub Slope >30% (SS)
 - Stream Cleaning (SC)
 - Water Bar (WB)
- Rehab Status**
- Rehab - Requires Field Verification
 - Rehab - Completed
- 4 Rehab Line Treatment (RLType)**
- Wetland (W)
 - Clean Drain (CD)
 - Danger Tree Treatment Required (DTA)
 - Dry Seed (DS)
 - Other Rehab Treatment Type
 - Pull Back (PB)
 - Road Damage - Requires Repair (RD)
 - Shrub Slope >30% (SS)
 - Stream Slope >30% (SS)
- 7 OFS Feature Type (FLTType)**
- Fireguard Machine Completed
 - Road - Modified Existing
 - Road - Newly Used

- 5 OFS Feature Type (FLTType)**
- Fireguard Machine Completed
 - Road - Modified Existing
 - Road - Newly Used
- 6 OFS Feature Type (FLTType)**
- Fireguard Machine Completed
 - Road - Modified Existing
 - Road - Newly Used
- 8 OFS Feature Type (FLTType)**
- Fireguard Machine Completed
 - Road - Modified Existing
 - Road - Newly Used
- 9 OFS Feature Type (FLTType)**
- Fireguard Machine Completed
 - Road - Modified Existing
 - Road - Newly Used
- 10 OFS Feature Type (FLTType)**
- Fireguard Machine Completed
 - Road - Modified Existing
 - Road - Newly Used



This map may contain
CONFIDENTIAL
information for INTERNAL
use only

Disclaimer:
This map was prepared by the author for the purpose of providing information only. It is not intended to be used for any other purpose. The author assumes no responsibility for any errors or omissions in this map. The user of this map assumes all responsibility for its use.

Map Date: February 27, 2023
Map Scale: 1:5,000