



BC Ministry of Forests and Range

Major Culvert Inspection Report

Page 1 of 2
Date Printed: 2015/12/23
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001C
File:

Structure #:	G1-343	Site #:	G1-343	Road Name:	MCGREGOR FSR	Inspection Date:	2015/08/13
KM:	29.50	User km:	27.60	Crossing Name:	Unnamed creek	Next Inspection Date:	2018/08/13
Project File ID #:	1817	Br.	01	Forest District:	Prince George Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	500			Outlet Cover (mm):	500		
Footing Type:				Gradient (%):			
Culvert Length (metres):	12.3	Opening Height (mm):	2,100	Opening Width (mm):	2,100		
UTM Zone:	10	UTM Easting:	600604	UTM Northing:	5993139		
Inspector Name:	Joe Vanderzwan			Year Superstructure Installed:	1980		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	


CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Good	Rivets.
Coupled Connections	Not Applicable	
Coating	Fair	
Embedment Materials	Good	
Fill	Good	
Floor	Unrated	Gravel bottom.
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Good	Inlet damaged but still functional.
Outlet	Good	
Overall	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.





BC Ministry of Forests and Range

Major Culvert Inspection Report

Page 2 of 2
Date Printed: 2015/12/23
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001C
File:

Structure #:	G1-343	Site #:	G1-343	Road Name:	MCGREGOR FSR	Inspection Date:	2015/08/13			
Riprap	Not Applicable									
Roof	Fair									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.1		Estimated Present Water Level Width:		1.8			
	Estimated High Water Level Clearance:		0.5							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
GENERAL	PEng's Comment:									
GENERAL	Replacement Date for full log haul traffic (year):			2025		Replacement Date for light vehicle traffic (year):				
	Current Inspection Load Rating:		91		Design Load GVW (tonnes):		91		Design Vehicle Config.: L100	
	Professional Inspection Required?		No		Report Status:		Reviewed By Jason Olmsted on 12/23/2015 8:45:13AM			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.