



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 1 of 3
Date Printed: 2015/12/17
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001A
File:

Structure #:	G1-634	Site #:	G1-634	Road Name:	SALMON FSR	Inspection Date:	2015/09/09
KM:	37.80	User km:	37.80	Crossing Name:	Unknown	Next Inspection Date:	2018/09/09
Project File ID #:	7727	Br.	01	Forest District:	Prince George Natural Resource District		
Deck Type:	Concrete Composite			Running Surface:	Concrete		
Superstructure	Steel I-beam			Abutments (Left/Right): (looking downstream)	Steel Pipe and Precast Pad		
Total Length (metres):	30.5	# Spans:	1	Span Length(s) (metres):	30.5		
UTM Zone:	10	UTM Easting:	499685	UTM Northing:	6019379		
Inspector Name:	Joe Vanderzwan			Year Superstructure Installed:	2007		
Access:							

ABUTMENTS

Bearings	Good	
Bracing	Good	
Ballast Wall	Good	
Corrosion Protection	Fair	
Caps or Sills	Unrated	N/A
Fill	Good	
Hardware	Not Applicable	
Piles or Posts	Good	
Riprap	Good	
Wing Wall	Not Applicable	

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	1	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	Good	
Posted Load Rating	L100	
Road Surface	Fair	


DECK

Span 1

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.





BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 2 of 3
Date Printed: 2015/12/17
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001A
File:

Structure #:	G1-634	Site #:	G1-634	Road Name:	SALMON FSR	Inspection Date:	2015/09/09			
Concrete Deck	Good									
Curb Rail/Blocks/Posts	Good									
Deck Joints	Fair									
Grout Pockets	Good									
Hardware	Not Applicable									
Hand Rails/Walkouts	Not Applicable									
Overall Deck Condition	Good									
Running Surface	Good									
SUPERSTRUCTURE										
Span 1										
Bracing	Good									
Diaphragms	Good									
Girders	Good									
Hardware	Good									
Under Trussing	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		1.0		Estimated Present Water Level Width:		10.0			
	Estimated High Water Level Clearance:		2.2							
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
	1	Required	Low	\$0.00	Replace missing bridge ahead sign					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.



BC Ministry of Forests and Range

Permanent Bridge Inspection Report

Page 3 of 3
Date Printed: 2015/12/17
User Id: IDIR\JOLMSTED
Database: PROD
Report Id: CBR001A
File:

Structure #:	G1-634	Site #:	G1-634	Road Name:	SALMON FSR	Inspection Date:	2015/09/09
GENERAL	PEng's Comment:						
GENERAL	Replacement Date for full log haul traffic (year):			2054	Replacement Date for light vehicle traffic (year):		
	Current Inspection Load Rating:		91	Design Load GVW (tonnes):		91	Design Vehicle Config.: L100
	Professional Inspection Required?		No	Report Status: Reviewed By Jason Olmsted on 12/17/2015 11:54:12AM			

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.