



BC Ministry of Forests and Range

Major Culvert Inspection Report

Page 1 of 2
Date Printed: 2015/11/03
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001C
File:

Structure #:	G1-638	Site #:	G1-638	Road Name:	STONE CREEK FSR	Inspection Date:	2015/06/18
KM:	5.90	User km:	3105.90	Crossing Name:	Unnamed creek	Next Inspection Date:	2018/06/18
Project File ID #:	4478	Br.	01	Forest District:	Prince George Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):	1.0		
Culvert Length (metres):	21.0	Opening Height (mm):	1,600	Opening Width (mm):	1,600		
UTM Zone:	10	UTM Easting:	526241	UTM Northing:	5940075		
Inspector Name:	Sean Hawryluk			Year Superstructure Installed:	1990		
Access:							

APPROACHES

Alignment	Fair	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	


CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Fair	Erosion of fill at inlet
Floor	Fair	Minor rust
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Fair	
Outlet	Poor	Perched ~80cm
Overall	Fair	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.





BC Ministry of Forests and Range

Major Culvert Inspection Report

Page 2 of 2
Date Printed: 2015/11/03
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001C
File:

Structure #:	G1-638	Site #:	G1-638	Road Name:	STONE CREEK FSR	Inspection Date:	2015/06/18			
Riprap	Not Applicable									
Roof	Good									
Side Walls	Fair		Minor damage							
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:		0.2		Estimated Present Water Level Width:		20.9			
	Estimated High Water Level Clearance:		0.2							
HAZARDS	High Water:	No	Scour:	Yes	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
	Replacement Date for full log haul traffic (year):				2025		Replacement Date for light vehicle traffic (year):			
	Current Inspection Load Rating:		91.00		Design Load GVW (tonnes):		91		Design Vehicle Config.:	
	Professional Inspection Required?		No		Report Status:		Accepted By Jason Olmsted on 11/3/2015 12:50:19PM			
Corporate Bridge Register (CBR)										

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.