



BC Ministry of Forests and Range

Major Culvert Inspection Report

Page 1 of 2
Date Printed: 2015/11/09
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001C
File:

Structure #:	G1-662	Site #:	G1-662	Road Name:	STONE-GOVERNMENT CR	Inspection Date:	2015/06/18
KM:	12.10	User km:	3212.00	Crossing Name:	Unnamed creek	Next Inspection Date:	2018/06/18
Project File ID #:	4478	Br.	05	Forest District:	Prince George Natural Resource District		
Culvert Type:	Round			Culvert Material:	Corrugated Steel		
Inlet Cover (mm):	1,000			Outlet Cover (mm):	1,000		
Footing Type:				Gradient (%):			
Culvert Length (metres):	20.0	Opening Height (mm):	2,200	Opening Width (mm):	2,200		
UTM Zone:	10	UTM Easting:	533742	UTM Northing:	5932495		
Inspector Name:	Sean Hawryluk			Year Superstructure Installed:	1994		
Access:							

APPROACHES

Alignment	Good	
Bridge Ahead Signs Missing	0	
Brushing Required	No	
Delineator Missing Left (approaching structure)	0	
Delineator Missing Right (approaching structure)	0	
Fender Condition	None	
Road Surface	Good	


CULVERT ELEMENT

Baffles	Not Applicable	
Bolted Connections	Not Applicable	
Coupled Connections	Good	
Coating	Fair	
Embedment Materials	Not Applicable	
Fill	Good	
Floor	Fair	Rusted, some cracks
Footing	Not Applicable	
Head Wall	Not Applicable	
Inlet	Fair	Rusted floor
Outlet	Fair	Rusted floor
Overall	Good	

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.





BC Ministry of Forests and Range

Major Culvert Inspection Report

Page 2 of 2
Date Printed: 2015/11/09
User Id: IDIRJOLMSTED
Database: PROD
Report Id: CBR001C
File:

Structure #:	G1-662	Site #:	G1-662	Road Name:	STONE-GOVERNMENT CR	Inspection Date:	2015/06/18			
Riprap	Good									
Roof	Good									
Side Walls	Good									
Trash Rack	Not Applicable									
Wiers/Backwater Structures	Not Applicable									
Wing Wall	Not Applicable									
CHANNEL	Estimated Present Water Level Depth:	0.7	Estimated Present Water Level Width:	1.3						
	Estimated High Water Level Clearance:	0.9								
HAZARDS	High Water:	No	Scour:	No	Ice:	No	Debris:	No	Aggradation:	No
	Comment:									
REPAIRS	#	Status	Priority	Estimate	Description					
MONITORS	#	Description								
GENERAL	Inspector's Comment:									
	Replacement Date for full log haul traffic (year):	2034	Replacement Date for light vehicle traffic (year):							
	Current Inspection Load Rating:	54.00	Design Load GVW (tonnes):	54	Design Vehicle Config.:					
	Professional Inspection Required?	No	Report Status:	Accepted By Jason Olmsted on 11/9/2015 4:04:08PM						

Corporate Bridge Register (CBR)

Disclaimer:

- 1) Structure and site information is current at the time of report creation and may have changed since the inspection was submitted and/or accepted.
- 2) Historic Load Rating data not available, contact FLNRO Regional Office for detailed information.