

QC-7133

CHADSEY MAIN 2.5km

2017 Inspection

CBR iPad Offline Ver



## CBR Data

Latitude 53°0'12.09" Longitude -131°58'29.1"

Crossing Name Unknown

FSR # 10843 Branch # 1

Road Name CHADSEY MAIN

User km 2.5

Current Load Rating (tonnes) 5

Structure Class Temporary Bridge

Portable N

Superstructure Log Stringers

Deck Type Gravel

Abutment Left Sill -Temporary Materials

Abutment Right Sill -Temporary Materials

Spans 1

Total Length (m) 8.2

Deck Width (m) 5.5

## Updated Data

Latitude 53°0'12.04" Longitude -131°58'29.04"

HD Diff. (m) 2.2 Accuracy (m) 5

Temporary Bridge

N

## Inspection

Date of Inspection 2017-09-12 10:13:32 AM

Recommended Next Inspection Year 2018

Inspector Name Mitch Lowe

Inspection Company Onsite Engineering Ltd

Inspector Comments

Suggest replacing with another log bridge due to approach constraints. Abutment require upgrades, but may be able to reuse stringers.

P.Eng Comments

Load Rated by: MFLNRO, J. Harvey, November 7, 2017

Load Rating: 5 Tonnes GVW

Next Inspection: September 1, 2020

Comments:



P.Eng Seal

QC-7133

CHADSEY MAIN 2.5km

2017 Inspection



CBR iPad Offline Ver

## Approach

Alignment Fair

Structure is in a steep vertical alignment.

Bridge Ahead Signs  
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required Y

Delineator Missing  
Left ☐ 0 ☐ 1 ☒ 2Delineator Missing  
Right ☐ 0 ☐ 1 ☒ 2

Fender Condition Poor

No approach barriers

Posted Load Rating

Not posted

Road Surface Good

## Abutment

Log/Timber Cribs N/A

Tie Backs

Bin Wall

Concrete

Caps or Sills Fair

Large Cw sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware Unrated

N/A

Fill

Riprap Poor

Left bank abutment is eroding on downstream side

Bearings Fair

Corrosion Protection

QC-7133

CHADSEY MAIN 2.5km

2017 Inspection

CBR iPad Offline Ver



## Deck

|                        |         |                                    |
|------------------------|---------|------------------------------------|
| Running Surface        | Fair    |                                    |
| Running Planks         | N/A     |                                    |
| Sub Deck               | N/A     |                                    |
| Ties                   | Unrated | N/A                                |
| Nails                  | Unrated | N/A                                |
| Deck to Girder Bolts   | Unrated | N/A                                |
| Concrete Deck          | Unrated | N/A                                |
| Grout Pockets          | N/A     |                                    |
| Deck Joints            | N/A     |                                    |
| Steel Deck Plate       | N/A     |                                    |
| Gravel Surface         | Fair    |                                    |
| Curb Rail/Blocks/Posts | Unrated | N/A                                |
| Hand Rails/Walkouts    | Unrated | N/A                                |
| Hardware               |         |                                    |
| Overall Deck Condition | Fair    | Hole on woods upstream end of deck |
| Gravel Depth (mm)      | .6      |                                    |

QC-7133

CHADSEY MAIN 2.5km

2017 Inspection



CBR iPad Offline Ver

**Steel/Concrete**

Serial/ID Plate

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted  
shear connectors**Log**

Log Curbs Fair

Needle Beam

Needle Lashing/  
Shimming Poor

No lashing

Needle Beam to Crib (m)

Needle Diameter (mm)

| Stringer<br>Number | Species | Peeled | Diameter<br>(mm) | Rot Depth<br>(mm) | Condition | Comment        |
|--------------------|---------|--------|------------------|-------------------|-----------|----------------|
| 1                  | Cw      | Y      | 770              | 50                | Poor      | Large cat face |
| 2                  | Cw      | Y      | 420              | 50                | Fair      |                |
| 3                  | Cw      | Y      | 610              | 50                | Fair      |                |
| 4                  | Cw      | Y      | 540              | 50                | Fair      |                |
| 5                  | Cw      | Y      | 580              | 50                | Fair      |                |
| 6                  | Cw      | Y      | 430              | 30                | Fair      |                |
| 7                  | Cw      | Y      | 370              | 30                | Fair      |                |
| 8                  | Cw      | Y      | 510              | 30                | Fair      |                |
| 9                  | Cw      | Y      | 610              | 30                | Fair      |                |
| 10                 | Cw      | Y      | 660              | 30                | Fair      |                |
| 11                 | Cw      | Y      | 530              | 30                | Poor      | Broken         |
| 12                 | Cw      | Y      | 700              | 30                | Fair      |                |
| 13                 | Cw      | Y      | 530              | 50                | Fair      |                |
| 14                 | Cw      | Y      | 510              | 30                | Fair      |                |

QC-7133

CHADSEY MAIN 2.5km

2017 Inspection

CBR iPad Offline Ver



## Hazards

|                                          |     |             |                                     |        |                                     |
|------------------------------------------|-----|-------------|-------------------------------------|--------|-------------------------------------|
| Estimated Present Water Level Depth (m)  | 0.3 | High Water  | <input checked="" type="checkbox"/> | Debris | <input checked="" type="checkbox"/> |
| Estimated Present Water Level Width (m)  | 8   | Aggradation | <input type="checkbox"/>            | Scour  | <input checked="" type="checkbox"/> |
| Estimated High Water Level Clearance (m) | 0.3 | Ice         | <input type="checkbox"/>            |        |                                     |

Comments

## Repairs and Monitoring

| Repair Item | Priority | Repair Description |
|-------------|----------|--------------------|
|-------------|----------|--------------------|

|   |      |                                       |
|---|------|---------------------------------------|
| 1 | High | Replace structure prior to active use |
|---|------|---------------------------------------|

|   |  |  |
|---|--|--|
| 2 |  |  |
|---|--|--|

|   |  |  |
|---|--|--|
| 3 |  |  |
|---|--|--|

| Item | Monitor Description          | Frequency          |
|------|------------------------------|--------------------|
| 1    | Monitor hole in road surface | Routine Inspection |
| 2    | Monitor broken stringer      | Routine Inspection |
| 3    | Monitor abutment erosion     | Routine Inspection |

Sketch  
(Select Signature)