

QC-7833

QC_MOS1000 3.7km

2017 Inspection

CBR iPad Offline Ver



CBR Data

Latitude	Longitude		
53°4'4.28"	-132°11'6.32"		
Crossing Name	Jovo Creek		
FSR #	10247	Branch #	1
Road Name	QC_MOS1000		
User km	3.7		
Current Load Rating (tonnes)	5		
Structure Class	Temporary Bridge		
Portable	N		
Superstructure	Log Stringers		
Deck Type	Gravel		
Abutment Left	Crib, Log or Untreated Timber		
Abutment Right	Crib, Log or Untreated Timber		
Spans	1		
Total Length (m)	11		
Deck Width (m)	4.5		

Updated Data

Latitude	Longitude		
53°4'4.53"	-132°11'6.38"		
HD Diff. (m)	7.7	Accuracy (m)	5
N	Log Stringer		
10.2	5		

Inspection

Date of Inspection 2017-09-12 12:34:22 PM

Recommended Next Inspection Year 2018

Inspector Name Mitch Lowe

Inspection Company Onsite Engineering Ltd

Inspector Comments

Unsure of why the load rating for this structure is reduced. Likely due to the abutment condition. Superstructure is in excellent shape and this structure could easily be upgraded to support haul trucks. Structure is well lashed.

P.Eng Comments

Load Rated by: MFLNRO, J. Harvey, November 7, 2017

Load Rating: 5 Tonnes GVW

Next Inspection: September 1, 2020

Comments: Replace stringer #7 to increase load rating



P.Eng Seal

QC-7833

QC_MOS1000 3.7km

2017 Inspection



CBR iPad Offline Ver

Approach

Alignment Good

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

Delineator Missing
Left ☐ 0 ☒ 1 ☐ 2Delineator Missing
Right ☐ 0 ☒ 1 ☐ 2

Fender Condition Good

Posted Load Rating 0 Load limit sign but no limit is written on the sign.

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills Good

Piles or Posts

Ballast Wall Good

Wing Wall

Bracing

Hardware Good

Fill

Riprap Poor Riprap on river left bank has completely eroded, leaving fill exposed and over steepened. High risk for erosion.

Bearings Good

Corrosion Protection

QC-7833

QC_MOS1000 3.7km

2017 Inspection

CBR iPad Offline Ver



Deck

Running Surface Good

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface Good

Curb Rail/Blocks/Posts Good

Hand Rails/Walkouts

Hardware

Overall Deck Condition Good

Gravel Depth (mm) 0.4

QC-7833

QC_MOS1000 3.7km

2017 Inspection



CBR iPad Offline Ver

Steel/Concrete

Serial/ID Plate

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**Log Curbs **Good**

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
1	Cw	Y	75	1		
2	Cw	Y	78	1		
3	Cw	Y	81	1		
4	Cw	Y	84	1		
5	Cw	Y	66	1		
6	Cw	Y	89	1		
7	Cw	Y	71	1		
8	Cw	Y	85	1		

QC-7833

QC_MOS1000 3.7km

2017 Inspection

CBR iPad Offline Ver



Hazards

Estimated Present Water Level Depth (m)	0.3	High Water	☒	Debris	☐
Estimated Present Water Level Width (m)	3	Aggradation	☐	Scour	☒
Estimated High Water Level Clearance (m)	1.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	Low	Replace 1 left hand and 1 right hand delineator.

2

3

Item	Monitor Description	Frequency
1	Monitor riprap on river left abutment.	Routine Inspection

2

3

Sketch
(Select Signature)