

QC-7111

BIL1200 0.39km

2018 Inspection



CBR iPad Offline Ver

CBR Data

Latitude	Longitude
53°48'25.59"	-132°23'3.5"
Crossing Name	Unknown
FSR #	10175
Branch #	03
Road Name	BIL1200
User km	0.39
Current Load Rating (tonnes)	36
Structure Class	Temporary Bridge
Portable	N
Superstructure	Timber - untreated stringers
Deck Type	Gravel
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	6
Deck Width (m)	5

Updated Data

Latitude	Longitude
53°48'25.38"	-132°23'3.67"
HD Diff. (m)	7.5
Accuracy (m)	5

Inspection

Date of Inspection 2018-09-19 1:43:27 PM

Inspector Name Robert Kemmler

Inspector Comments Serial/ID Plate

Cw Log bridge is in fair condition. Low soffit and high water prevented a detailed inspection of the stringers.

Recommended Next Inspection Year 2020

Inspection Company Onsite Engineering

P.Eng Comments

Load Rated by: MFLNRO, J. Harvey P.Eng., February 5, 2018

Load Rating: 36 Tonnes GVW

Next Inspection: September 1, 2020

Comments: Stringers are undersized for span. Replace stringers with MINIMUM 470mm diameter to gain L-60 load rating with 350mm gravel depth.

Post Load rating signs



QC-7111

BIL1200 0.39km

2018 Inspection



CBR iPad Offline Ver

Approach

Alignment Fair

Bridge Ahead Signs
Missing 0 1 • 2

Brushing Required Y

Delineator Missing
Left 0 1 • 2

Delineator Missing
Right 0 1 • 2

Fender Condition Poor None

Posted Load Rating 0 Not posted

Road Surface Fair

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Concrete N/A

Caps or Sills Good Large Cw sills on organic material.

Piles or Posts N/A

Ballast Wall N/A

Wing Wall N/A

Bracing N/A

Hardware N/A

Fill Good

Riprap N/A

Bearings Good

Corrosion Protection N/A

QC-7111

BIL1200 0.39km

2018 Inspection



CBR iPad Offline Ver

Deck

Running Surface	N/A	
Running Planks	N/A	
Sub Deck	N/A	
Ties	N/A	
Nails	N/A	
Deck to Girder Bolts	N/A	
Concrete Deck	N/A	
Grout Pockets	N/A	
Deck Joints	N/A	
Steel Deck Plate	N/A	
Gravel Surface	Fair	
Curb Rail/Blocks/Posts	Poor	None
Hand Rails/Walkouts	N/A	
Hardware	N/A	
Overall Deck Condition	Poor	Due to the lack of curbs.
Gravel Depth (mm)	300	

QC-7111

BIL1200 0.39km

2018 Inspection



CBR iPad Offline Ver

Steel/Concrete

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**Log Curbs **Poor**

No curb logs

Needle Beam **N/A**Needle Lashing/
Shimming

Needle Beam to Crib (m)

Stringer Number	Species	Peeled	Diameter (mm)	Needle Diameter (mm) Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	---	-----------	---------

QC-7111

BIL1200 0.39km

2018 Inspection



CBR iPad Offline Ver

Hazards

Estimated Present Water Level Depth (m)	0.4	High Water	Debris
Estimated Present Water Level Width (m)	1.5	Aggradation	Scour
Estimated High Water Level Clearance (m)	1.0	Ice	

Comments

Repairs and Monitoring

Repair

Item Priority

Repair Description

- | | | |
|---|--------|--|
| 1 | High | Add curb logs |
| 2 | Medium | Install bridge ahead signs and delineators on both approaches. |
| 3 | | |

Item

Monitor Description

Frequency

1

2

3

Sketch
(Select Signature)