

QC-7115

GREGORY 2.2km

2018 Inspection



CBR iPad Offline Ver

CBR Data

Latitude 53°24'7.09" Longitude -132°27'10.3"

Crossing Name Unknown

FSR # 8229 Branch # 04

Road Name GREGORY

User km 2.2

Current Load Rating (tonnes) 5

Structure Class Woodbox/Log Culvert

Portable N

Superstructure

Deck Type

Abutment Left

Abutment Right

Spans 0

Total Length (m) 7

Deck Width (m)

Updated Data

Latitude °0'0" Longitude °0'0"

HD Diff. (m) 5944680.3 Accuracy (m)

Inspection

Date of Inspection 2018-09-16 7:44:47 AM

Inspector Name Robert Kemmler

Recommended Next Inspection Year 2019


Inspection Company Onsite Engineering

Inspector Comments Serial/ID Plate

Unable to access structure. Gregory FSR blocked by a slide at 1.3km.
Re-inspect when Road opens up.

P.Eng Comments

Load Rated by: MFLNRO, J. Harvey P.Eng., February 5, 2018
Load Rating: 0 Tonnes GVW
Next Inspection: September 1, 2019
Comments: Inspect when road reopens

February 6 2019
P.Eng Seal

QC-7115

GREGORY 2.2km

2018 Inspection



CBR iPad Offline Ver

Approach

Alignment

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☐ 2

Brushing Required

Delineator Missing
Left ☐ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☐ 0 ☐ 1 ☐ 2

Fender Condition

Posted Load Rating

Road Surface

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill

Riprap

Bearings

Corrosion Protection

QC-7115

GREGORY 2.2km

2018 Inspection

CBR iPad Offline Ver



Deck

Running Surface

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts

Hand Rails/Walkouts

Hardware

Overall Deck Condition

Gravel Depth (mm)

QC-7115

GREGORY 2.2km

2018 Inspection



CBR iPad Offline Ver

Steel/Concrete

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Stringer
Number

Species

Peeled

Diameter
(mm)Needle Diameter (mm)
Rot Depth
(mm)

Condition

Comment

QC-7115

GREGORY 2.2km

2018 Inspection



CBR iPad Offline Ver

Hazards

Estimated Present Water Level Depth (m)	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	Ice	☐		
Comments				

Repairs and Monitoring

Repair Item	Priority	Repair Description
1		

2

3

Item	Monitor Description	Frequency
1		
2		
3		

Sketch
(Select Signature)