

QC-7127

EY6 0.7km

2018 Inspection



CBR iPad Offline Ver

CBR Data

Latitude 53°36'48.3" Longitude -132°10'19.2"

Crossing Name Unknown

FSR # 10845 Branch # 04

Road Name EY6

User km 0.7

Current Load Rating (tonnes) 91

Structure Class Temporary Bridge

Portable N

Superstructure Log Stringers

Deck Type Other

Abutment Left Pile - Temporary Materials

Abutment Right Pile - Temporary Materials

Spans 1

Total Length (m) 14.8

Deck Width (m) 5.5

Updated Data

Latitude 53°36'47.96" Longitude -132°10'19.33"

HD Diff. (m) 10.7 Accuracy (m) 5

Inspection

Date of Inspection 2018-09-17 4:09:39 PM

Inspector Name Robert Kemmler

Recommended Next Inspection Year 2020

Inspection Company Onsite Engineering

Inspector Comments Serial/ID Plate

Cw Log Bridge with cross puncheon. Cross puncheon extends approximately 1m beyond stringers both sides. Some maintenance issues around signage, brushing and fill depths over deck but other wise no concerns.

P.Eng Comments

Load Rated by: MFLNRO, J. Harvey P.Eng., February 5, 2018

Load Rating: 91 Tonnes GVW

Next Inspection: September 1, 2020

Comments: Clean growth off deck, along side fill retention logs, add 200-300mm of gravel fill. Brush approaches and install bridge ahead signs.



QC-7127

EY6 0.7km

2018 Inspection



CBR iPad Offline Ver

Approach

Alignment Fair

 Bridge Ahead Signs
Missing 0 ☐ 1 ☒ 2

Brushing Required Y

 Delineator Missing
Left • 0 ☐ 1 ☐ 2

 Delineator Missing
Right • 0 ☐ 1 ☐ 2

Fender Condition Poor None

Posted Load Rating 0 None posted

Road Surface Fair

Abutment

Log/Timber Cribbs Fair

Cw cribs Built on top of Cw piles. Bottom of cribs consist of two Cw logs through bolted together.

Tie Backs Fair

Bin Wall N/A

Concrete N/A

Caps or Sills N/A

Piles or Posts Fair

Cw piles drives at random, ie: not in line.

Ballast Wall N/A

Wing Wall Fair

Bracing Fair

Hardware Fair

Through bolts with end plates.

Fill Fair

Riprap N/A

Bearings Fair

Corrosion Protection N/A

QC-7127

EY6 0.7km

2018 Inspection



CBR iPad Offline Ver

Deck

Running Surface	N/A	
Running Planks	N/A	
Sub Deck	N/A	
Ties	N/A	
Nails	N/A	
Deck to Girder Bolts	N/A	
Concrete Deck	N/A	
Grout Pockets	N/A	
Deck Joints	N/A	
Steel Deck Plate	N/A	
Gravel Surface	Fair	Two pot holes at midspan reduce fill to 100mm
Curb Rail/Blocks/Posts	Fair	Brush growing up along side of curbs making them invisible
Hand Rails/Walkouts	N/A	
Hardware	N/A	
Overall Deck Condition	Fair	
Gravel Depth (mm)	250	Minimum 300mm required with cross puncheon

QC-7127

EY6 0.7km

2018 Inspection



CBR iPad Offline Ver

Steel/Concrete

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**Log Curbs **Fair**Needle Beam **N/A**Needle Lashing/
Shimming

Needle Beam to Crib (m)

Stringer Number	Species	Peeled	Diameter (mm)	Needle Diameter (mm) Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	---	-----------	---------

QC-7127

EY6 0.7km

2018 Inspection



CBR iPad Offline Ver

Hazards

Estimated Present Water Level Depth (m)	0.5	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	2.5	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	2.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	High	Clean growth off deck, along side fill retention logs, add 200-300mm of gravel fill.
2	Medium	Brush approaches and install bridge ahead signs
3		

Item	Monitor Description	Frequency
1	Monitor "goofy" abutments for settling and or forward rotation.	Routine Inspection
2		
3		

Sketch
(Select Signature)