

QC-7402

GREGORY 4.9km

2018 Inspection



CBR iPad Offline Ver

CBR Data

Latitude	Longitude
53°24'26.6"	-132°26'13.3"
Crossing Name	Gregory 200
FSR #	8229
Branch #	04
Road Name	GREGORY
User km	4.9
Current Load Rating (tonnes)	68
Structure Class	Temporary Bridge
Portable	N
Superstructure	Log Stringers
Deck Type	Gravel
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	7.2
Deck Width (m)	6

Updated Data

Latitude	Longitude
°0'0"	°0'0"
HD Diff. (m)	5945283.3
Accuracy (m)	

Inspection

Date of Inspection 2018-09-16 8:10:02 AM

Inspector Name Robert Kemmler

Inspector Comments Serial/ID Plate

Unable to access. Gregory FSR is blocked @ 1.3km by a slide.
Re-inspect when road opens up.

Recommended Next Inspection Year 2019

Inspection Company Onsite Engineering

P.Eng Comments

Load Rated by: MFLNRO, J. Harvey P.Eng., February 5, 2018

Load Rating: 68 Tonnes GVW

Next Inspection: September 1, 2019

Comments: Reinspect next season



February 6 2019

QC-7402

GREGORY 4.9km

2018 Inspection



CBR iPad Offline Ver

Approach

Alignment

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☐ 2

Brushing Required

Delineator Missing
Left ☐ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☐ 0 ☐ 1 ☐ 2

Fender Condition

Posted Load Rating

Road Surface

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill

Riprap

Bearings

Corrosion Protection

QC-7402

GREGORY 4.9km

2018 Inspection



CBR iPad Offline Ver

Deck

Running Surface

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts

Hand Rails/Walkouts

Hardware

Overall Deck Condition

Gravel Depth (mm)

QC-7402

GREGORY 4.9km

2018 Inspection



CBR iPad Offline Ver

Steel/Concrete

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/ Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

QC-7402

GREGORY 4.9km

2018 Inspection



CBR iPad Offline Ver

Hazards

Estimated Present Water Level Depth (m)

High Water

☐

Debris

☐

Estimated Present Water Level Width (m)

Aggradation

☐

Scour

☐

Estimated High Water Level Clearance (m)

Ice

☐

Comments

Repairs and Monitoring

Repair

Item

Priority

Repair Description

1

2

3

Item

Monitor Description

Frequency

1

2

3

Sketch
(Select Signature)