

QC-7501

BONANZA/BILL BROWN 16.9km

2018 Inspection



CBR iPad Offline Ver

CBR Data

Latitude	Longitude
53°25'45"	-132°34'39.9"
Crossing Name	Bill Brown Creek?
FSR #	8229
Branch #	01
Road Name	BONANZA/BILL BROWN
User km	16.9
Current Load Rating (tonnes)	5
Structure Class	Temporary Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Timber - Untreated
Abutment Left	Crib, Log or Untreated Timber
Abutment Right	Crib, Log or Untreated Timber
Spans	1
Total Length (m)	27.1
Deck Width (m)	4.2

Updated Data

Latitude	Longitude
53°25'46.05"	-132°34'41.04"
HD Diff. (m)	38.7
Accuracy (m)	5

Inspection

Date of Inspection 2018-09-15 2:18:49 PM

Inspector Name Robert Kemmler

Recommended Next Inspection Year 2020

Inspection Company Onsite Engineering

Inspector Comments Serial/ID Plate MOF L-60, WO-274, 26.6m, May, 92. (26.11m)

P.Eng Comments

Load Rated by: MFLNRO, J. Harvey P.Eng., February 5, 2018

Load Rating: 5 Tonnes GVW

Next Inspection: September 1, 2020

Comments: Replace all wooden deck components



QC-7501

BONANZA/BILL BROWN 16.9km

2018 Inspection



CBR iPad Offline Ver

Approach

Alignment **Good**Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2Brushing Required **Y** Road quad access only for 120m.Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2Fender Condition **Poor** **None**Posted Load Rating **0** **Not posted**Road Surface **Poor** **Grown in**

Abutment

Log/Timber Cribs **Fair** 3cm sap rot on crib logs.Tie Backs **Fair**Bin Wall **N/A**Concrete **N/A**Caps or Sills **Good** **Creosote timbers**Piles or Posts **N/A**Ballast Wall **Good** **Creosote timbers**Wing Wall **N/A**Bracing **N/A**Hardware **Fair**Fill **Good**Riprap **N/A**Bearings **Good**Corrosion Protection **N/A**

QC-7501

BONANZA/BILL BROWN 16.9km

2018 Inspection



CBR iPad Offline Ver

Deck

Running Surface	Poor	Grown in
Running Planks	Poor	Rotten
Sub Deck	Poor	Rotten
Ties	Poor	Rotten
Nails	Fair	
Deck to Girder Bolts	Fair	
Concrete Deck	N/A	
Grout Pockets	N/A	
Deck Joints	N/A	
Steel Deck Plate	N/A	
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	Poor	Rotten
Hand Rails/Walkouts	N/A	
Hardware	Fair	
Overall Deck Condition	Poor	Deck should be replaced prior to industrial activity.
Gravel Depth (mm)	0	

CBR iPad Offline Ver



Girders	Good
Diaphragms	Good
Bracing	Good
Under Trussing	N/A
Hardware	Good
Welded/grouted shear connectors	N/A

Log Curbs

Needle Beam

Needle Lashing/ Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
-----------------	---------	--------	---------------	----------------	-----------	---------

QC-7501

BONANZA/BILL BROWN 16.9km

2018 Inspection



CBR iPad Offline Ver

Hazards

Estimated Present Water Level Depth (m)	0.5	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	5.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	6	Ice	☐		

Comments

Repairs and Monitoring

Repair

Item Priority

Repair Description

1	High	Replace cross ties, sub-deck, running planks, riders, blocks and guard rails prior to industrial activity.
---	------	--

2

3

Item

Monitor Description

Frequency

1

2

3

Sketch
(Select Signature)