

QC-7503

BONANZA/BILL BROWN 8.43km

2018 Inspection



CBR iPad Offline Ver

CBR Data

Latitude	Longitude
53°24'7.27"	-132°30'56"
Crossing Name	Unknown
FSR #	8229
Branch #	01
Road Name	BONANZA/BILL BROWN
User km	8.43
Current Load Rating (tonnes)	150
Structure Class	Permanent Bridge
Portable	N
Superstructure	Concrete Slab Girders
Deck Type	Concrete
Abutment Left	Concrete Precast
Abutment Right	Concrete Precast
Spans	1
Total Length (m)	11
Deck Width (m)	5.63

Updated Data

Latitude	Longitude
53°24'7"	-132°30'57.18"
HD Diff. (m)	23.4
Accuracy (m)	5
	4.88

Inspection

Date of Inspection 2018-09-16 10:12:42 AM

Inspector Name Robert Kemmler

Recommended Next Inspection Year 2021

Inspection Company Onsite Engineering

Inspector Comments Serial/ID Plate BCTS, CHE-0015B, L-165, 11-12-080, March 2012, 11 Meters.

P.Eng Comments

Load Rated by: MFLNRO, J. Harvey P.Eng., February 5, 2018

Load Rating: 150 Tonnes GVW

Next Inspection: September 1, 2021

Comments:



QC-7503

BONANZA/BILL BROWN 8.43km

2018 Inspection



CBR iPad Offline Ver

ApproachAlignment **Good**Bridge Ahead Signs
Missing • 0 ☒ 1 ☐ 2Brushing Required **N**Delineator Missing
Left • 0 ☒ 1 ☐ 2Delineator Missing
Right • 0 ☒ 1 ☐ 2Fender Condition **Good**Posted Load Rating **0** No load limit postedRoad Surface **Fair** Potholes on both approaches exposing the ends of the girders**Abutment**Log/Timber Cribs **N/A**Tie Backs **N/A**Bin Wall **N/A**Concrete **Good** Integrated cap and ballast wall.Caps or Sills **Good** ConcretePiles or Posts **N/A**Ballast Wall **Good** ConcreteWing Wall **N/A**Bracing **N/A**Hardware **N/A**Fill **Good**Riprap **Good**Bearings **Good**Corrosion Protection **N/A**

QC-7503

BONANZA/BILL BROWN 8.43km

2018 Inspection

CBR iPad Offline Ver

**Deck**

Running Surface	Good	Potholes on both approaches exposing the ends of the girders
Running Planks	N/A	
Sub Deck	N/A	
Ties	N/A	
Nails	N/A	
Deck to Girder Bolts	N/A	
Concrete Deck	Good	Based on the age of structure. Unable to fully assess due to gravel/mud on deck.
Grout Pockets	Unrated	Unable to assess due to gravel/mud on deck.
Deck Joints	Unrated	Unable to assess due to gravel/mud on deck.
Steel Deck Plate	N/A	
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	Good	
Hand Rails/Walkouts	N/A	
Hardware	N/A	
Overall Deck Condition	Good	
Gravel Depth (mm)	0	

QC-7503

BONANZA/BILL BROWN 8.43km

2018 Inspection



CBR iPad Offline Ver

Steel/Concrete

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

QC-7503

BONANZA/BILL BROWN 8.43km

2018 Inspection



CBR iPad Offline Ver

Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	Debris
Estimated Present Water Level Width (m)	0.3	Aggradation	Scour
Estimated High Water Level Clearance (m)	1.5	Ice	

Comments

Repairs and Monitoring

Repair

Item Priority

Repair Description

1 Medium Grade In potholes on approaches to prevent damage to the ends of girders.

2

3

Item

Monitor Description

Frequency

1

2

3

Sketch
(Select Signature)