

QC-7609

HANGOVER 5.4km

2018 Inspection



CBR iPad Offline Ver

CBR Data

Latitude 53°27'25.49" Longitude -132°32'51.9"

Crossing Name Unknown

FSR # 8229 Branch # 06

Road Name HANGOVER

User km 5.4

Current Load Rating (tonnes) 5

Structure Class Woodbox/Log Culvert

Portable N

Superstructure

Deck Type

Abutment Left

Abutment Right

Spans 0

Total Length (m) 10.4

Deck Width (m)

Updated Data

Latitude 53°27'26.24" Longitude -132°32'52.03"

HD Diff. (m) 23.2 Accuracy (m) 10

Inspection

Date of Inspection 2018-09-15 12:52:44 PM

Inspector Name Robert Kemmler

Inspector Comments Serial/ID Plate

Road is grown in, will require quad access in 2020

Recommended Next Inspection Year 2020

Inspection Company Onsite Engineering

P.Eng Comments

Load Rated by: MFLNRO, J. Harvey P.Eng., February 5, 2018

Load Rating: 5 Tonnes GVW

Next Inspection: September 1, 2020

Comments:



QC-7609

HANGOVER 5.4km

2018 Inspection



CBR iPad Offline Ver

Approach

Alignment **Poor**

Turn on camp approach

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2Brushing Required **Y**Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2Fender Condition **Poor**

No approach barriers

Posted Load Rating **5**Road Surface **Fair**

Abutment

Log/Timber Cribs **N/A**Tie Backs **N/A**Bin Wall **N/A**Concrete **N/A**Caps or Sills **Good** **Single Cw sills**Piles or Posts **N/A**Ballast Wall **N/A**Wing Wall **N/A**Bracing **N/A**Hardware **N/A**Fill **Good**Riprap **N/A**Bearings **Good**Corrosion Protection **N/A**

QC-7609**HANGOVER 5.4km****2018 Inspection**

CBR iPad Offline Ver

Deck

Running Surface	Fair
Running Planks	N/A
Sub Deck	N/A
Ties	N/A
Nails	N/A
Deck to Girder Bolts	N/A
Concrete Deck	N/A
Grout Pockets	N/A
Deck Joints	N/A
Steel Deck Plate	N/A
Gravel Surface	Good
Curb Rail/Blocks/Posts	Fair
Hand Rails/Walkouts	N/A
Hardware	N/A
Overall Deck Condition	Fair
Gravel Depth (mm)	1.0

CBR iPad Offline Ver

2018 Inspection



Comment

QC-7609

HANGOVER 5.4km

2018 Inspection



CBR iPad Offline Ver

Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	0.3	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	0	Ice	☐		

Comments

Repairs and Monitoring

Repair

Item Priority

Repair Description

- | | | |
|---|--------|---|
| 1 | High | Replace prior to industrial activity. |
| 2 | Medium | Consider brushing camp approach to reveal load rating sign. |

3

Item

Monitor Description

Frequency

1

2

3

Sketch
(Select Signature)