

QC-7829

MORESBY 3.1km

2018 Inspection



CBR iPad Offline Ver

CBR Data

Latitude	Longitude
53°5'53.19"	-132°2'56.7"
Crossing Name	Shale Creek Side Channel
FSR #	10308 Branch # 01
Road Name	MORESBY
User km	3.1
Current Load Rating (tonnes)	150
Structure Class	Permanent Bridge
Portable	N
Superstructure	Concrete Slab Girders
Deck Type	Concrete
Abutment Left	Concrete Lock Blocks
Abutment Right	Concrete Lock Blocks
Spans	1
Total Length (m)	11
Deck Width (m)	5

Updated Data

Latitude	Longitude
53°5'53.18"	-132°2'57.69"
HD Diff. (m)	18.4 Accuracy (m) 5

Inspection

Date of Inspection 2018-09-14 1:23:40 PM

Inspector Name Robert Kemmler

Inspector Comments Serial/ID Plate

Recommended Next Inspection Year 2021

Inspection Company Onsite Engineering

P.Eng Comments

Load Rated by: MFLNRO, J. Harvey P.Eng., February 5, 2018

Load Rating: 150 Tonnes GVW

Next Inspection: September 1, 2021

Comments:



February 6 2019

QC-7829

MORESBY 3.1km

2018 Inspection



CBR iPad Offline Ver

Approach

Alignment **Good**

Bridge Ahead Signs
Missing • 0 ☒ 1 ☐ 2

Brushing Required **Y**

Delineator Missing
Left • 0 ☒ 1 ☐ 2

Delineator Missing
Right • 0 ☒ 1 ☐ 2

Fender Condition **Good**

Posted Load Rating **0.0**

Road Surface **Fair**

Abutment

Log/Timber Cribs **N/A**

Tie Backs **N/A**

Bin Wall **N/A**

Concrete **Good**

Caps or Sills **Good**

Piles or Posts **Good**

Ballast Wall **Good**

Wing Wall **N/A**

Bracing **N/A**

Hardware **N/A**

Fill **N/A**

Riprap **Good**

Bearings **Good**

Corrosion Protection **Good**

QC-7829

MORESBY 3.1km

2018 Inspection



CBR iPad Offline Ver

Deck

Running Surface	Good
Running Planks	N/A
Sub Deck	N/A
Ties	N/A
Nails	N/A
Deck to Girder Bolts	N/A
Concrete Deck	Good
Grout Pockets	N/A
Deck Joints	Good
Steel Deck Plate	N/A
Gravel Surface	N/A
Curb Rail/Blocks/Posts	Good
Hand Rails/Walkouts	N/A
Hardware	Good
Overall Deck Condition	Good
Gravel Depth (mm)	0

QC-7829

MORESBY 3.1km

2018 Inspection



CBR iPad Offline Ver

Steel/Concrete

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors**Good**

Welded shear keys

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

QC-7829

MORESBY 3.1km

2018 Inspection



CBR iPad Offline Ver

Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	2.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	2.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1	Low	Minor brushing required.
---	-----	--------------------------

2		
---	--	--

3		
---	--	--

Item	Monitor Description	Frequency
------	---------------------	-----------

1		
---	--	--

2		
---	--	--

3		
---	--	--

Sketch
(Select Signature)