

QC-7113

BONANZA 21.2km

2019 Inspection

CBR iPad Offline Ver



CBR Data

Latitude	Longitude		
53°29'11.4"	-132°30'17"		
Crossing Name	Not Known		
FSR #	8229	Branch #	07
Road Name	BONANZA		
User km	21.2		
Previous Load Rating (tonnes)	150		
Structure Class	Major Culvert		
Culvert Type	Round		
Culvert Material	Corrugated Steel		
Opening Height (mm)	2200		
Opening Width (mm)	2200		
Inlet Cover (mm)	1400		
Outlet Cover (mm)	2600		
Culvert Gradient %	5		
Culvert Length (m)	18		

Updated Data

Latitude	Longitude		
53°29'10.8"	-132°30'16.19"		
HD Diff. (m)	23.8	Accuracy (m)	5
1100			
2200			
10			
21			

Inspection

Date of Inspection 2019-09-16 11:09:36 AM

Inspector Name Lindsey McGill

Recommended Next Inspection Year 2022

Inspection Company Chartwell Consultants Ltd.

Inspector Comments

Road fill requires maintenance, culvert is stable.

P.Eng Comments

Load Rated by: FLNRORD, J. Harvey P.Eng., February 13, 2020

Load Rating: 150 Tonnes GVW

Next Inspection: September 1, 2022

Comments: Fill hole in road



P.Eng Seal

QC-7113

BONANZA 21.2km

2019 Inspection



CBR iPad Offline Ver

Approach

Alignment Good

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

Delineator Missing
Left ☐ 0 ☐ 1 ☒ 2

Delineator Missing
Right ☐ 0 ☐ 1 ☒ 2

Fender Condition Unrated None present

Posted Load Rating

Road Surface Fair Hole in road from failed cross puncheon, 5m past cmp on high chain side.

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall N/A

Bracing

Hardware

Fill Good

Riprap Good

Bearings

Corrosion Protection

QC-7113

BONANZA 21.2km

2019 Inspection

CBR iPad Offline Ver



Culvert

Baffles	N/A	
Bolted Connections	N/A	
Coating	Fair	Galvanized but rust present
Coupled Connections	Fair	Minor gaps but does not appear to be leaking.
Embedment Materials	N/A	
Fill	Good	
Floor	Fair	Rust present but no holes.
Footing	Fair	
Head Walls	N/A	
Inlet	Good	Bevelled inlet
Outlet	Good	Bevelled outlet, bedrock below outlet.
Overall	Good	
Rip Rap	Good	
Roof	Good	Shape is elliptical due to deformation from road fills.
Sidewalls	Fair	Shape is elliptical due to deformation from road fills.
Trash Rack	N/A	
Weirs/Backwater Structures	N/A	
Wing Walls	N/A	

QC-7113

BONANZA 21.2km

2019 Inspection

CBR iPad Offline Ver



Log

Log Curbs N/A

Needle Beam N/A

Needle Lashing/
Shimming N/A

Needle Beam to Crib (m)			Needle Diameter (mm)			
Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment

QC-7113

BONANZA 21.2km

2019 Inspection

CBR iPad Offline Ver



Hazards

Estimated Present Water Level Depth (m) .15

High Water ☐Debris ☐

Estimated Present Water Level Width (m) 1.5

Aggradation ☐Scour ☐

Estimated High Water Level Clearance (m) 1.6

Ice ☐

Comments

Repairs and Monitoring

Repair

Item Priority

Repair Description

1

2

3

Item

Monitor Description

Frequency

1 Monitor for further deformation

Routine Inspection

2

3

Sketch
(Select Signature)

QC-7113

BONANZA 21.2km

2019 Inspection



CBR iPad Offline Ver



Upstream Profile



Looking upstream through culvert



Approach from Left Bank when facing downstream



Downstream Profile

QC-7113

BONANZA 21.2km

2019 Inspection

CBR iPad Offline Ver



Upstream from Crossing



Hole in road



Downstream from Crossing



Approach from Right Bank when facing downstream



QC-7113

BONANZA 21.2km

2019 Inspection

CBR iPad Offline Ver



QC-7113

BONANZA 21.2km

2019 Inspection



CBR iPad Offline Ver

QC-7113

BONANZA 21.2km

2019 Inspection



CBR iPad Offline Ver