

QC-7857

Lawn North 9.35km

2019 Inspection

CBR iPad Offline Ver



CBR Data

Latitude	Longitude		
53°25'58.59"	-131°59'42.9"		
Crossing Name	Unknown		
FSR #	10118	Branch #	01
Road Name	Lawn North		
User km	9.35		
Previous Load Rating (tonnes)	10		
Structure Class	Temporary Bridge		
Portable	N		
Superstructure	Log Stringers		
Deck Type	Gravel		
Abutment Left	Sill -Temporary Materials		
Abutment Right	Sill -Temporary Materials		
Spans	1		
Total Length (m)	11		
Deck Width (m)	5		

Updated Data

Latitude	Longitude		
53°25'58.83"	-131°59'44.07"		
HD Diff. (m)	22.6	Accuracy (m)	5
1			
9			
5.6			

Inspection

Date of Inspection 2019-09-07 3:24:48 PM

Recommended Next Inspection Year 2022

Inspector Name Lindsey McGill

Inspection Company Chartwell Consultants Ltd.

Inspector Comments Serial/ID Plate

Appears to be generally well built. Since spruce stringers are not peeled, expect a reduced lifespan for crossing. Additional set of brow logs placed on inside of pinned brow logs acting to minimize overall road width. Updated total length is actually the Center-Center span (c/c=9.0m, o/a=11.0m).

P.Eng Comments

Load Rated by: FLNRORD, J. Harvey P.Eng., February 13, 2020
 Load Rating: 136 Tonnes GVW
 Next Inspection: September 1, 2021
 Comments: Updated load rating from recent stringer measurements



P.Eng Seal

QC-7857

Lawn North 9.35km

2019 Inspection



CBR iPad Offline Ver

Approach

Alignment Good

 Bridge Ahead Signs
Missing ☐ 0 ☒ 1 ☐ 2

Brushing Required N

 Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

 Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Fair

Posted Load Rating 10 This sign is old and was removed by the inspector.

Road Surface Good

Abutment

Log/Timber Cribs Good Single spruce sill logs

Tie Backs N/A

Bin Wall N/A

Pier N/A

Concrete N/A

Caps or Sills N/A

Piles or Posts N/A

Ballast Wall N/A

Wing Wall N/A

Bracing N/A

Hardware Good Drill steel visible on corners of brow logs

Fill Good

Riprap Good Large diameter riprap that is angular. Stream is relatively slow moving.

Bearings Good Stringers bear level on sills.

Corrosion Protection N/A

QC-7857

Lawn North 9.35km

2019 Inspection

CBR iPad Offline Ver

**Deck**

Running Surface	Good	
Running Planks	N/A	
Sub Deck	N/A	
Ties	N/A	
Nails	N/A	
Deck to Girder Bolts	N/A	
Concrete Deck	N/A	
Grout Pockets	N/A	
Deck Joints	N/A	
Steel Deck Plate	N/A	
Gravel Surface	Good	Fill is coarse rock but no concerns (6" minus)
Curb Rail/Blocks/Posts	Good	Spruce logs
Hand Rails/Walkouts	N/A	
Hardware	N/A	
Overall Deck Condition	Good	
Gravel Depth (mm)	500	
Pier Deck		

QC-7857

Lawn North 9.35km

2019 Inspection

CBR iPad Offline Ver



Steel/Concrete

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs Good

Needle Beam N/A

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

1	Sp	N	880	0	Fair	Lots of knots present
2	Sp	N	940	0	Fair	Some spiral twist present
3	Sp	N	785	0	Good	
4	Sp	N	780	0	Good	A few knots present
5	Sp	N	825	0	Good	
6	Sp	N	795	0	Good	
7	Sp	N	755	0	Good	
8	Sp	N	800	0	Good	
9	Sp	N	755	0	Good	

QC-7857

Lawn North 9.35km

2019 Inspection

CBR iPad Offline Ver



Hazards

Estimated Present Water Level Depth (m)	.3	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	3	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.0	Ice	☐		

Comments No stringers are peeled but they are all new within the last year or so. Ends of stringers appear to be gut lashed with old haulback cable. Browlogs are secured with drift pins at each end.

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	Medium	Install proper signage for load rating

2

3

Item	Monitor Description	Frequency
1		
2		
3		

Sketch
(Select Signature)

A handwritten signature in black ink, appearing to read "W. M. J. N." or similar.



Upstream from Crossing



Approach from Left Bank when facing downstream



Downstream from Crossing





Approach from Right Bank when facing downstream



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream



Upstream Profile

QC-7857

Lawn North 9.35km

2019 Inspection

CBR iPad Offline Ver



Downstream Profile



Stringers



QC-7857

Lawn North 9.35km

2019 Inspection



CBR iPad Offline Ver

QC-7857

Lawn North 9.35km

2019 Inspection

CBR iPad Offline Ver

