

SC-8061

MCNAB 11.94km

2019 Inspection

CBR iPad Offline Ver 0.31



CBR Data

Latitude	Longitude
49°39'37.1"	-123°25'48.3"
Crossing Name	Unknown
FSR #	10209
Branch #	1
Road Name	MCNAB
User km	11.94
Previous Load Rating (tonnes)	150
Structure Class	Major Culvert
Culvert Type	Open Bottom
Culvert Material	Corrugated Steel
Opening Height (mm)	1910
Opening Width (mm)	3660
Inlet Cover (mm)	1300
Outlet Cover (mm)	1300
Culvert Gradient %	1.9
Culvert Length (m)	20

Updated Data

Latitude	Longitude
°0'0"	°0'0"
HD Diff. (m)	5528160.0
Accuracy (m)	

Inspection

Date of Inspection 2019-10-15 12:16:19 PM

Inspector Name Richard Mills


Inspector Comments

Recommended Next Inspection Year

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: Forrest Simpson, EIT, Mar 6, 2020
Load Rating: L165 or 150 tonnes
Next Inspection: 2022



P.Eng Seal

SC-8061

MCNAB 11.94km

2019 Inspection



CBR iPad Offline Ver 0.31

Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☐ 0 ☐ 1 ☒ 2

Delineator Missing
Right ☐ 0 ☐ 1 ☒ 2

Fender Condition Good

Posted Load Rating

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall N/A

Bracing

Hardware

Fill Good

Riprap Good

Bearings

Corrosion Protection

SC-8061

MCNAB 11.94km

2019 Inspection

CBR iPad Offline Ver 0.31

**Culvert**

Baffles N/A

Bolted Connections Good

Coating Good

Coupled Connections N/A

Embedment Materials N/A

Fill Good

Floor Good

Footing Good

Head Walls N/A

Inlet Good

Outlet Good

Overall Good

Rip Rap Good

Roof Good

Sidewalls Good

Trash Rack N/A

Weirs/Backwater
Structures N/A

Wing Walls N/A

SC-8061

MCNAB 11.94km

2019 Inspection

CBR iPad Offline Ver 0.31



Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SC-8061

MCNAB 11.94km

2019 Inspection

CBR iPad Offline Ver 0.31



Hazards

Estimated Present Water Level Depth (m) 0.1

High Water ☐Debris ☐

Estimated Present Water Level Width (m) 0.5

Aggradation ☐Scour ☐

Estimated High Water Level Clearance (m) 1.8

Ice ☐

Comments

Repairs and Monitoring

Repair

Item Priority

Repair Description

1 Medium Add delineators to approach barriers

2

3

Item

Monitor Description

Frequency

1

2

3

Sketch
(Select Signature)

SC-8061

MCNAB 11.94km

2019 Inspection



CBR iPad Offline Ver 0.31

Inlet



Inlet



Outlet



Inlet



SC-8061

MCNAB 11.94km

2019 Inspection

CBR iPad Offline Ver 0.31



Approach from Right Bank when facing downstream