

SC-8206

THEODOSIA 2.5km

2019 Inspection

CBR iPad Offline Ver 0.31



CBR Data

Latitude	Longitude
49°56'8"	-124°37'0"
Crossing Name	Not Known
FSR #	6423
Branch #	10
Road Name	THEODOSIA
User km	2.5
Previous Load Rating (tonnes)	68
Structure Class	Major Culvert
Culvert Type	Elliptical
Culvert Material	Corrugated Steel
Opening Height (mm)	2690
Opening Width (mm)	3890
Inlet Cover (mm)	950
Outlet Cover (mm)	1000
Culvert Gradient %	
Culvert Length (m)	15.3

Updated Data

Latitude	Longitude
°0'0"	°0'0"
HD Diff. (m)	5558800.7
Accuracy (m)	

Inspection

Date of Inspection 2019-10-07 2:35:32 PM

Inspector Name Richard Mills


Inspector Comments

Recommended Next Inspection Year

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: Forrest Simpson, EIT, Mar 3, 2020
Load Rating: L75 or 68 tonnes
Next Inspection: 2022



P.Eng Seal

SC-8206

THEODOSIA 2.5km

2019 Inspection



CBR iPad Offline Ver 0.31

Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Unrated N/a

Posted Load Rating

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall Good

Bracing

Hardware

Fill Good

Riprap Good

Bearings

Corrosion Protection

SC-8206

THEODOSIA 2.5km

2019 Inspection

CBR iPad Offline Ver 0.31

**Culvert**

Baffles N/A

Bolted Connections Good

Coating Fair Floor is worn

Coupled Connections N/A

Embedment Materials N/A

Fill Good

Floor Fair

Footing Good

Head Walls Good

Inlet Good

Outlet Good

Overall Good

Rip Rap Good

Roof Good

Sidewalls Good

Trash Rack N/A

Weirs/Backwater
Structures N/A

Wing Walls Good

SC-8206

THEODOSIA 2.5km

2019 Inspection

CBR iPad Offline Ver 0.31



Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SC-8206

THEODOSIA 2.5km

2019 Inspection

CBR iPad Offline Ver 0.31



Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	1.5	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.8	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)

SC-8206

THEODOSIA 2.5km


2019 Inspection



CBR iPad Offline Ver 0.31



Approach from Left Bank when facing downstream



Approach from Left Bank when facing downstream



Inlet



Inlet

SC-8206

THEODOSIA 2.5km

2019 Inspection

CBR iPad Offline Ver 0.31



Outlet



SC-8206

THEODOSIA 2.5km

2019 Inspection

CBR iPad Offline Ver 0.31



SC-8206

THEODOSIA 2.5km

2019 Inspection



CBR iPad Offline Ver 0.31

SC-8206

THEODOSIA 2.5km

2019 Inspection

CBR iPad Offline Ver 0.31

