

SC-8226

THEODOSIA 0.65km

2019 Inspection



CBR iPad Offline Ver 0.31

CBR Data

Latitude	Longitude
49°59'35.9"	-124°37'58.1"
Crossing Name	Not Known
FSR #	6423
Branch #	3
Road Name	THEODOSIA
User km	0.65
Previous Load Rating (tonnes)	150
Structure Class	Permanent Bridge
Portable	N
Superstructure	Concrete Slab Girders
Deck Type	Concrete
Abutment Left	Concrete Lock Blocks
Abutment Right	Concrete Lock Blocks
Spans	1
Total Length (m)	10.7
Deck Width (m)	4.8

Updated Data

Latitude	Longitude
°0'0"	°0'0"
HD Diff. (m)	5565229.4
Accuracy (m)	

Inspection

Date of Inspection 2019-10-08 10:38:37 AM

Inspector Name Richard Mills


Inspector Comments Serial/ID Plate

Recommended Next Inspection Year

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: Forrest Simpson, EIT, Mar 5, 2020
Load Rating: L165 or 150 tonnes
Next Inspection: 2022
Comments: Replace guardrails.



P.Eng Seal

SC-8226

THEODOSIA 0.65km

2019 Inspection



CBR iPad Offline Ver 0.31

Approach

Alignment Good

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required Y

Delineator Missing
Left ☐ 0 ☒ 1 ☐ 2Delineator Missing
Right ☐ 0 ☒ 1 ☐ 2

Fender Condition Good

Posted Load Rating

Road Surface Fair

Alders in deck

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Pier N/A

Concrete Good

Caps or Sills Fair Treated timber

Piles or Posts N/A

Ballast Wall N/A

Wing Wall N/A

Bracing N/A

Hardware Good

Fill Good

Riprap Good

Bearings Fair Treated timber

Corrosion Protection N/A

SC-8226

THEODOSIA 0.65km

2019 Inspection

CBR iPad Offline Ver 0.31

**Deck**

Running Surface	Fair	Alders in deck
-----------------	------	----------------

Running Planks	N/A	
----------------	-----	--

Sub Deck	N/A	
----------	-----	--

Ties	N/A	
------	-----	--

Nails	N/A	
-------	-----	--

Deck to Girder Bolts	N/A	
----------------------	-----	--

Concrete Deck	Unrated	Unable to see
---------------	---------	---------------

Grout Pockets	N/A	
---------------	-----	--

Deck Joints	Good	
-------------	------	--

Steel Deck Plate	N/A	
------------------	-----	--

Gravel Surface	Good	
----------------	------	--

Curb Rail/Blocks/Posts	Poor	Rotten rails
------------------------	------	--------------

Hand Rails/Walkouts	N/A	
---------------------	-----	--

Hardware	Good	
----------	------	--

Overall Deck Condition	Fair	
------------------------	------	--

Gravel Depth (mm)		
-------------------	--	--

Pier Deck		
-----------	--	--

SC-8226

THEODOSIA 0.65km

2019 Inspection



CBR iPad Offline Ver 0.31

Steel/Concrete

Girders Fair

Concrete slabs. Flaws in casting

Diaphragms N/A

Bracing N/A

Under Trussing N/A

Hardware Good

Welded/grouted
shear connectors Good**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

SC-8226

THEODOSIA 0.65km

2019 Inspection

CBR iPad Offline Ver 0.31



Hazards

Estimated Present Water Level Depth (m)	0.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	2.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
1	High	Replace guardrails

2

3

Item	Monitor Description	Frequency
1		

2

3

Sketch
(Select Signature)

Superstructure



Left Bank Abutment when facing downstream



Superstructure

