

SC-8335

STAKAWUS 4.9km

2019 Inspection

CBR iPad Offline Ver 0.31



CBR Data

Latitude	Longitude		
50°3'6"	-123°44'13"		
Crossing Name	Not Known		
FSR #	7443	Branch #	1
Road Name	STAKAWUS		
User km	4.9		
Previous Load Rating (tonnes)	136		
Structure Class	Temporary Bridge		
Portable	Y		
Superstructure	Steel Truss/Bailey/Acrow		
Deck Type	Concrete		
Abutment Left	Crib, Log or Untreated Timber		
Abutment Right	Crib, Log or Untreated Timber		
Spans	1		
Total Length (m)	12.2		
Deck Width (m)	4.9		

Updated Data

Latitude	Longitude	
°0'0"	°0'0"	
HD Diff. (m)	5571726.1	Accuracy (m)

Inspection

Date of Inspection 2019-10-15 9:46:14 AM

Inspector Name Richard Mills

Recommended Next Inspection Year


Inspection Company FLNRORD

Inspector Comments Serial/ID Plate

Unable to land due to brushed -in Road. Bridge appears ok from air.

P.Eng Comments

Load Rated by: MFLNRO Richard Mills P.Eng., Mar 10th, 2020
 Load Rating: TBD
 Next Inspection: 2020
 Comments: Unable to access site.



P.Eng Seal

SC-8335

STAKAWUS 4.9km

2019 Inspection



CBR iPad Offline Ver 0.31

Approach

Alignment

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☐ 2

Brushing Required

Delineator Missing
Left ☐ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☐ 0 ☐ 1 ☐ 2

Fender Condition

Posted Load Rating

Road Surface

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill

Riprap

Bearings

Corrosion Protection

SC-8335

STAKAWUS 4.9km

2019 Inspection

CBR iPad Offline Ver 0.31



Deck

Running Surface

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts

Hand Rails/Walkouts

Hardware

Overall Deck Condition

Gravel Depth (mm)

Pier Deck

SC-8335

STAKAWUS 4.9km

2019 Inspection

CBR iPad Offline Ver 0.31

**Steel/Concrete**

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

SC-8335

STAKAWUS 4.9km

2019 Inspection

CBR iPad Offline Ver 0.31



Hazards

Estimated Present Water Level Depth (m)

High Water

☐

Debris

☐

Estimated Present Water Level Width (m)

Aggradation

☐

Scour

☐

Estimated High Water Level Clearance (m)

Ice

☐

Comments

Repairs and Monitoring

Repair

Item Priority

Repair Description

1

2

3

Item

Monitor Description

Frequency

1

2

3

Sketch
(Select Signature)