

SC-8340

HALFMOON CARLSON 3km

2019 Inspection

CBR iPad Offline Ver 0.28



CBR Data

Latitude	Longitude
49°30'9.29"	-123°50'11.5"
Crossing Name	Wakefield Creek
FSR #	6003
Branch #	3
Road Name	HALFMOON CARLSON
User km	3
Current Load Rating (tonnes)	136
Structure Class	Permanent Bridge
Portable	N
Superstructure	Concrete Slab Girders
Deck Type	Concrete
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	10
Deck Width (m)	4.89

Updated Data

Latitude	Longitude
°0'0"	°0'0"
HD Diff. (m)	5510602.3
Accuracy (m)	

Inspection

Date of Inspection 2019-04-12 10:27:51 AM

Inspector Name Richard Mills


Inspector Comments Serial/ID Plate

Recommended Next Inspection Year

Inspection Company MFLNRO

P.Eng Comments

Load Rated by: Forrest Simpson, EIT, Mar 2, 2020
Load Rating: L150 or 136 tonnes
Next Inspection: 2022



P.Eng Seal

SC-8340

HALFMOON CARLSON 3km

2019 Inspection



CBR iPad Offline Ver 0.28

Approach

Alignment Good

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Concrete Good

Caps or Sills Good

Piles or Posts Unrated Unable to see

Ballast Wall Good

Wing Wall

Bracing

Hardware

Fill Good

Riprap Good

Bearings Good

Corrosion Protection

SC-8340

HALFMOON CARLSON 3km

2019 Inspection

CBR iPad Offline Ver 0.28

**Deck**Running Surface **Good**

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck **Good** Minor chipping end of slab left abutment approach

Grout Pockets

Deck Joints **Good**

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts **Good**

Hand Rails/Walkouts

Hardware **Good**Overall Deck Condition **Good**

Gravel Depth (mm)

SC-8340

HALFMOON CARLSON 3km

2019 Inspection

CBR iPad Offline Ver 0.28

**Steel/Concrete**Girders **Good**

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

SC-8340

HALFMOON CARLSON 3km

2019 Inspection

CBR iPad Offline Ver 0.28



Hazards

Estimated Present Water Level Depth (m)	0.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	2.2	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.8	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)



Approach from Right Bank when facing downstream



Right Bank Abutment when facing downstream



Approach from Left Bank when facing downstream



Left Bank Abutment when facing downstream



Inlet



Approach from Left Bank when facing downstream