

SC-8639

2019 Inspection



CBR iPad Offline Ver 0.26

CBR Data

Latitude	Longitude
°0'0"	°0'0"
Crossing Name	
FSR #	Branch #
Road Name	
User km	
Current Load Rating (tonnes)	None
Structure Class	
Portable	
Superstructure	
Deck Type	
Abutment Left	
Abutment Right	
Spans	
Total Length (m)	
Deck Width (m)	

Updated Data

Latitude	Longitude
49°26'6"	-123°32'6.15"
HD Diff. (m)	10058457.6
Accuracy (m)	5
7.5	

Inspection

Date of Inspection 2019-04-11 3:10:29 PM

Inspector Name Richard Mills

Recommended Next Inspection Year 2021


Inspection Company MFLNRO

Inspector Comments

No rot stringers

P.Eng Comments

Load Rated by: Forrest Simpson, EIT, Mar 2, 2020
Load Rating: L150 or 136 tonnes
Next Inspection: 2021



P.Eng Seal

SC-8639

2019 Inspection



CBR iPad Offline Ver 0.26

Approach

Alignment Good

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☐ 0 ☒ 1 ☐ 2

Fender Condition Good

Posted Load Rating

Road Surface Good

Abutment

Log/Timber Cribs Good

Tie Backs Good

Bin Wall

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill Good

Riprap Fair Ds right undermined. Monitor

Bearings

Corrosion Protection

SC-8639

2019 Inspection

CBR iPad Offline Ver 0.26



Deck

Running Surface **Good**

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface **Good**

Curb Rail/Blocks/Posts **Good**

Hand Rails/Walkouts

Hardware

Overall Deck Condition **Good**

Gravel Depth (mm) **450**

SC-8639

2019 Inspection



CBR iPad Offline Ver 0.26

Steel/Concrete

Serial/ID Plate

Girders Good

Corners pinned

Diaphragms

Bracing

Under Trussing

Hardware Good

Lashing tight

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
-----------------	---------	--------	---------------	----------------	-----------	---------

1	Fd		630			
2	Fd		550			
3	Fd		720			
4	Fd		800			
5	Fd		800			
6	Fd		760			
7	Fd		800			
8	Fd		680			
9	Fd		670			
10	Fd		710			
11	Fd		650			
12	Fd		610			

SC-8639

2019 Inspection



CBR iPad Offline Ver 0.26

Hazards

Estimated Present Water Level Depth (m)	0.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	1.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	2.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
1	Monitor ds right abutment crb	Routine Inspection

2

3

Sketch
(Select Signature)



Approach from Left Bank when facing downstream



Right Bank Abutment when facing downstream



Inlet



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream