

SC-8032

HALFMOON CARLSON 0.5km

2020 Inspection



CBR iPad Offline Ver 0.31

CBR Data

Latitude	Longitude
49°32'19.39"	-123°52'40.5"
Crossing Name	Not Known
FSR #	6003
Branch #	2
Road Name	HALFMOON CARLSON
User km	0.5
Previous Load Rating (tonnes)	136
Structure Class	Major Culvert
Culvert Type	Round
Culvert Material	Corrugated Steel
Opening Height (mm)	2400
Opening Width (mm)	2400
Inlet Cover (mm)	1800
Outlet Cover (mm)	2300
Culvert Gradient %	
Culvert Length (m)	18

Updated Data

Latitude	Longitude
°0'0"	°0'0"
HD Diff. (m)	5514625.3
Accuracy (m)	

Inspection

Date of Inspection 2020-11-05 4:03:51 PM

Inspector Name Richard Mills


Inspector Comments

Recommended Next Inspection Year

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Feb 18, 2021
Load Rating: L150 or 136 tonnes
Next Inspection: 2023



P.Eng Seal

SC-8032

HALFMOON CARLSON 0.5km

2020 Inspection



CBR iPad Offline Ver 0.31

Approach

Alignment Good

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Unrated Na

Posted Load Rating

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall N/A

Bracing

Hardware

Fill Good

Riprap Good

Bearings

Corrosion Protection

SC-8032

HALFMOON CARLSON 0.5km

2020 Inspection

CBR iPad Offline Ver 0.31

**Culvert**

Baffles N/A

Bolted Connections N/A

Coating Fair

Coupled Connections Good

Embedment Materials N/A

Fill Good

Floor Fair Minor Corrosion

Footing Good

Head Walls N/A

Inlet Good

Outlet Good

Overall Good

Rip Rap Good

Roof Good

Sidewalls Good

Trash Rack N/A

Weirs/Backwater
Structures N/A

Wing Walls N/A

SC-8032

HALFMOON CARLSON 0.5km

2020 Inspection

CBR iPad Offline Ver 0.31



Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SC-8032

HALFMOON CARLSON 0.5km

2020 Inspection

CBR iPad Offline Ver 0.31



Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	0.5	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.8	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
1	Monitor corrosion on floor	Routine Inspection

2

3

Sketch
(Select Signature)

SC-8032

HALFMOON CARLSON 0.5km

2020 Inspection



CBR iPad Offline Ver 0.31



Approach from Left Bank when facing downstream



Outlet



Inlet



High voltage cable nearby

SC-8032

HALFMOON CARLSON 0.5km

2020 Inspection

CBR iPad Offline Ver 0.31



SC-8032

HALFMOON CARLSON 0.5km

2020 Inspection

CBR iPad Offline Ver 0.31



SC-8032

HALFMOON CARLSON 0.5km

2020 Inspection



CBR iPad Offline Ver 0.31

SC-8032

HALFMOON CARLSON 0.5km

2020 Inspection

CBR iPad Offline Ver 0.31

