

SC-8250

ROBERTS FLUME 2.4km

2020 Inspection



CBR iPad Offline Ver 0.31

CBR Data

Latitude	Longitude
49°27'26.79"	-123°37'8"
Crossing Name	Upper Clack Creek
FSR #	8546
Branch #	1
Road Name	ROBERTS FLUME
User km	2.4
Previous Load Rating (tonnes)	68
Structure Class	Temporary Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Concrete Composite
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	18.3
Deck Width (m)	4.88

Updated Data

Latitude	Longitude
°0'0"	°0'0"
HD Diff. (m)	5505577.5
Accuracy (m)	

Inspection

Date of Inspection 2020-11-05 2:05:42 PM

Inspector Name Richard Mills


Inspector Comments Serial/ID Plate

Recommended Next Inspection Year

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Feb 18, 2021
Load Rating: L75 or 68 tonnes
Next Inspection: 2023



P.Eng Seal

SC-8250

ROBERTS FLUME 2.4km

2020 Inspection



CBR iPad Offline Ver 0.31

Approach

Alignment Fair

Corner

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete Good

Caps or Sills Good

Piles or Posts Good

Ballast Wall Good

Wing Wall

Bracing Good

Hardware Good

Fill Good

Riprap Good

Bearings Good

Corrosion Protection Good

SC-8250

ROBERTS FLUME 2.4km

2020 Inspection

CBR iPad Offline Ver 0.31



Deck

Running Surface Fair

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck Good

Grout Pockets Good

Deck Joints Good

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Good

Hand Rails/Walkouts

Hardware Good

Overall Deck Condition Good

Gravel Depth (mm)

Pier Deck

SC-8250

ROBERTS FLUME 2.4km

2020 Inspection

CBR iPad Offline Ver 0.31

**Steel/Concrete**

Girders Good

Diaphragms Good

Bracing Good

Under Trussing

Hardware Good

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

SC-8250

ROBERTS FLUME 2.4km

2020 Inspection

CBR iPad Offline Ver 0.31



Hazards

Estimated Present Water Level Depth (m)	0.3	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	3.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	3.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)

SC-8250

ROBERTS FLUME 2.4km

2020 Inspection



CBR iPad Offline Ver 0.31

Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



Upstream Profile



Deck



SC-8250

ROBERTS FLUME 2.4km

2020 Inspection

CBR iPad Offline Ver 0.31



Right Bank Abutment when facing downstream

SC-8250

ROBERTS FLUME 2.4km

2020 Inspection

CBR iPad Offline Ver 0.31



SC-8250

ROBERTS FLUME 2.4km

2020 Inspection

CBR iPad Offline Ver 0.31



SC-8250

ROBERTS FLUME 2.4km

2020 Inspection

CBR iPad Offline Ver 0.31

