

SC-8624

2020 Inspection

CBR iPad Offline Ver 0.32



CBR Data

Latitude Longitude
°0'0" °0'0"
Crossing Name
FSR # Branch #
Road Name
User km
Previous Load Rating (tonnes) None
Structure Class
Portable
Superstructure
Deck Type
Abutment Left
Abutment Right
Spans
Total Length (m)
Deck Width (m)

Updated Data

Latitude Longitude
°0'0" °0'0"
HD Diff. (m) 10018754.2 Accuracy (m)

Inspection

Date of Inspection 2020-11-05 10:06:35 AM

Inspector Name Richard Mills


Inspector Comments Serial/ID Plate

Recommended Next Inspection Year 2022

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Mar 8, 2021
Load Rating: L100 or 91 tonnes
Next Inspection: 2022



P.Eng Seal

SC-8624

2020 Inspection



CBR iPad Offline Ver 0.32

Approach

Alignment **Good**

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required **N**

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition **Fair** **Small**

Posted Load Rating

Road Surface **Good** **Cross - ditched**

Abutment

Log/Timber Cribs **Good**

Tie Backs **Good**

Bin Wall

Pier

Concrete

Caps or Sills **Good**

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware **Good**

Fill **Good**

Riprap **Good**

Bearings **Good**

Corrosion Protection

SC-8624

2020 Inspection

CBR iPad Offline Ver 0.32



Deck

Running Surface Good Cross - ditched

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface Good

Curb Rail/Blocks/Posts Good

Hand Rails/Walkouts

Hardware Good

Overall Deck Condition Good

Gravel Depth (mm) 400

Pier Deck

SC-8624

2020 Inspection

CBR iPad Offline Ver 0.32

**Steel/Concrete**

Girders Good Stringers less than 10mm sap rot

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors**Log**

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)Rot Depth
(mm)

Condition

Comment

SC-8624

2020 Inspection



CBR iPad Offline Ver 0.32

Hazards

Estimated Present Water Level Depth (m)	0.2	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	1.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	3.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Priority	Repair Description
-------------	----------	--------------------

1

2

3

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

Sketch
(Select Signature)



Left Bank Abutment when facing downstream



Approach from Left Bank when facing downstream



Right Bank Abutment when facing downstream



Approach from Right Bank when facing downstream

SC-8624

2020 Inspection

CBR iPad Offline Ver 0.32



SC-8624

2020 Inspection

CBR iPad Offline Ver 0.32



SC-8624

2020 Inspection

CBR iPad Offline Ver 0.32



SC-8624

2020 Inspection



CBR iPad Offline Ver 0.32