

SC-8012
SC-8012

DUCK LAKE 9.9km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



CBR Data

Latitude	Longitude
49°51'9.69"	-124°25'37.2"
Crossing Name	Mud Lake
FSR #	3477
Branch #	01
Road Name	DUCK LAKE
User km	9.9
Previous Load Rating (tonnes)	150
Structure Class	Permanent Bridge
Portable	N
Superstructure	Concrete Slab Girders
Deck Type	Concrete
Abutment Left	Pile -Permanent Materials
Abutment Right	Pile -Permanent Materials
Spans	1
Total Length (m)	11.7
Deck Width (m)	4.9

Updated Data

Latitude	Longitude
49°51'10.41"	-124°25'37.64"
HD Diff. (m)	23.8
Accuracy (m)	9

Inspection

Date of Inspection 2021-10-05 12:07:11 PM

Inspector Name Forrest Simpson

Inspector Comments Serial/ID Plate

Recommended Next Inspection Year 2024

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Jan 4, 2022
Load Rating: L165 or 150 tonnes
Next Inspection: 2024



P.Eng Seal

SC-8012
SC-8012

DUCK LAKE 9.9km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Approach

Alignment **Good**

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required **N**

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition **Good**

Posted Load Rating **None**

Road Surface **Good**

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete **Good**

Caps or Sills **Good**

Piles or Posts **Unrated** **Not visible**

Ballast Wall **Good**

Wing Wall

Bracing

Hardware

Fill **Good**

Riprap **Good**

Bearings **Good**

Corrosion Protection

SC-8012
SC-8012

DUCK LAKE 9.9km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Deck

Running Surface **Fair**

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck **Good**

Grout Pockets

Deck Joints **Good**

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts **Fair**

Hand Rails/Walkouts

Hardware **Good**

Overall Deck Condition **Good**

Gravel Depth (mm)

Pier Deck

SC-8012
SC-8012

DUCK LAKE 9.9km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Steel/Concrete

Girders **Good**

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors **Good**

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SC-8012
SC-8012

DUCK LAKE 9.9km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Hazards

Estimated Present Water Level Depth (m)	.5	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	5	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.2	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

SC-8012
SC-8012

DUCK LAKE 9.9km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Approach from Right Bank when facing downstream




Approach from Left Bank when facing downstream



Left Bank Abutment when facing downstream



Deck



SC-8012
SC-8012

DUCK LAKE 9.9km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Downstream from Crossing



Right Bank Abutment when facing downstream



Upstream from Crossing



Superstructure



SC-8012
SC-8012

DUCK LAKE 9.9km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



SC-8012
SC-8012

DUCK LAKE 9.9km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



SC-8012
SC-8012

DUCK LAKE 9.9km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



SC-8012
SC-8012

DUCK LAKE 9.9km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC

