

SC-8190
SC-8190

TEXADA ISLAND 0.26km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



CBR Data

Latitude	Longitude
49°36'47.99"	-124°18'58.1"
Crossing Name	Not Known
FSR #	5829
Branch #	09
Road Name	TEXADA ISLAND
User km	0.26
Previous Load Rating (tonnes)	136
Structure Class	Major Culvert
Culvert Type	Elliptical
Culvert Material	Corrugated Steel
Opening Height (mm)	1400
Opening Width (mm)	2130
Inlet Cover (mm)	1800
Outlet Cover (mm)	1000
Culvert Gradient %	1
Culvert Length (m)	12

Updated Data

Latitude	Longitude
°0'0"	°0'0"
HD Diff. (m)	5522931.0
Accuracy (m)	

Inspection

Date of Inspection 2021-05-14 12:42:39 PM

Inspector Name Richard Mills


Inspector Comments

Recommended Next Inspection Year 2024

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. May 26, 2021
Load Rating: L150 or 136 tonnes
Next Inspection: 2024



P.Eng Seal

SC-8190
SC-8190

TEXADA ISLAND 0.26km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Approach

Alignment Good

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Unrated Na

Posted Load Rating

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall N/A

Bracing

Hardware

Fill Good

Riprap Good

Bearings

Corrosion Protection

SC-8190
SC-8190

TEXADA ISLAND 0.26km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Culvert

Baffles N/A

Bolted Connections N/A

Coating Fair

Coupled Connections N/A

Embedment Materials Good

Fill Good

Floor Fair

Footing Good

Head Walls N/A

Inlet Good

Outlet Good

Overall Good

Rip Rap Good

Roof Good

Sidewalls Good

Trash Rack N/A

Weirs/Backwater
Structures N/A

Wing Walls N/A

SC-8190
SC-8190

TEXADA ISLAND 0.26km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SC-8190
SC-8190

TEXADA ISLAND 0.26km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Hazards

Estimated Present Water Level Depth (m)

High Water

☐

Debris

☐

Estimated Present Water Level Width (m)

Aggradation

☐

Scour

☐

Estimated High Water Level Clearance (m)

Ice

☐

Comments

Repairs and Monitoring

Repair Item

Repair Description

1

2

3

4

5

6

7

Item

Monitor Description

Frequency

1

2

3

SC-8190
SC-8190

TEXADA ISLAND 0.26km

2021 Inspection


CBR iPad Offline Ver 0.34 - DSC



Outlet



Inlet



Inlet



SC-8190
SC-8190

TEXADA ISLAND 0.26km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



SC-8190
SC-8190

TEXADA ISLAND 0.26km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



SC-8190
SC-8190

TEXADA ISLAND 0.26km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



SC-8190
SC-8190

TEXADA ISLAND 0.26km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



SC-8190
SC-8190

TEXADA ISLAND 0.26km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC

