

SC-8193
SC-8193

TEXADA ISLAND 25.1km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



CBR Data

Latitude	Longitude
49°32'2.79"	-124°9'5.2"
Crossing Name	Not Known
FSR #	5829
Branch #	03
Road Name	TEXADA ISLAND
User km	25.1
Previous Load Rating (tonnes)	136
Structure Class	Permanent Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Concrete Composite
Abutment Left	Steel Pipe and Precast Pad
Abutment Right	Steel Pipe and Precast Pad
Spans	1
Total Length (m)	12.3
Deck Width (m)	4.88

Updated Data

Latitude	Longitude
°0'0"	°0'0"
HD Diff. (m)	5514112.0
Accuracy (m)	

Inspection

Date of Inspection 2021-05-20 11:09:49 AM

Inspector Name Richard Mills


Inspector Comments Serial/ID Plate

Recommended Next Inspection Year 2024

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. June 3, 2021
Load Rating: L150 or 136 tonnes
Next Inspection: 2024



P.Eng Seal

SC-8193
SC-8193

TEXADA ISLAND 25.1km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Approach

Alignment Good

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating

Road Surface Good

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Pier N/A

Concrete Good

Caps or Sills Good

Piles or Posts Good

Ballast Wall Good

Wing Wall N/A

Bracing Good

Hardware Good

Fill Good

Riprap Good

Bearings Good

Corrosion Protection Good

SC-8193
SC-8193

TEXADA ISLAND 25.1km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Deck

Running Surface Good

Running Planks N/A

Sub Deck N/A

Ties N/A

Nails N/A

Deck to Girder Bolts N/A

Concrete Deck Good

Grout Pockets Good

Deck Joints Good

Steel Deck Plate N/A

Gravel Surface N/A

Curb Rail/Blocks/Posts Good

Hand Rails/Walkouts N/A

Hardware Good

Overall Deck Condition Good

Gravel Depth (mm)

Pier Deck N/A

SC-8193
SC-8193

TEXADA ISLAND 25.1km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Steel/Concrete

Girders Good

Diaphragms Good

Bracing Good

Under Trussing N/A

Hardware Good

Welded/grouted
shear connectors N/A

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SC-8193
SC-8193

TEXADA ISLAND 25.1km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	1.2	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	2.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item

Monitor Description

Frequency

1

2

3

SC-8193
SC-8193

TEXADA ISLAND 25.1km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



Deck



Left Bank Abutment when facing downstream

SC-8193
SC-8193

TEXADA ISLAND 25.1km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Right Bank Abutment when facing downstream

SC-8193
SC-8193

TEXADA ISLAND 25.1km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



SC-8193
SC-8193

TEXADA ISLAND 25.1km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



SC-8193
SC-8193

TEXADA ISLAND 25.1km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



SC-8193
SC-8193

TEXADA ISLAND 25.1km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC

