

SC-8217
SC-8217

THEODOSIA 9.1km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



CBR Data

Latitude	Longitude
49°58'34.2"	-124°35'20"
Crossing Name	Not Known
FSR #	6423
Branch #	01
Road Name	THEODOSIA
User km	9.1
Previous Load Rating (tonnes)	150
Structure Class	Major Culvert
Culvert Type	Open Bottom
Culvert Material	Corrugated Steel
Opening Height (mm)	1870
Opening Width (mm)	4570
Inlet Cover (mm)	1000
Outlet Cover (mm)	1000
Culvert Gradient %	4
Culvert Length (m)	14

Updated Data

Latitude	Longitude
°0'0"	°0'0"
HD Diff. (m)	5563321.5
Accuracy (m)	

Inspection

Date of Inspection 2021-04-08 10:56 AM

Inspector Name Richard Mills


Inspector Comments

Recommended Next Inspection Year

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Apr 20, 2021
Load Rating: L165 or 150 tonnes
Next Inspection: 2024



P.Eng Seal

SC-8217
SC-8217

THEODOSIA 9.1km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y Road becoming brushed in

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Unrated Na

Posted Load Rating

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall N/A

Bracing

Hardware

Fill Good

Riprap N/A

Bearings

Corrosion Protection

SC-8217
SC-8217

THEODOSIA 9.1km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Culvert

Baffles	N/A	
Bolted Connections	Good	
Coating	Good	
Coupled Connections	N/A	
Embedment Materials	N/A	
Fill	Good	
Floor	Good	
Footing	Good	
Head Walls	N/A	
Inlet	Good	Small dent inlet, likely construction-related
Outlet	Good	
Overall	Good	
Rip Rap	N/A	
Roof	Good	
Sidewalls	Good	
Trash Rack	N/A	
Weirs/Backwater Structures	N/A	
Wing Walls	N/A	

SC-8217
SC-8217

THEODOSIA 9.1km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SC-8217
SC-8217

THEODOSIA 9.1km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	1.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

SC-8217
SC-8217

THEODOSIA 9.1km

2021 Inspection


CBR iPad Offline Ver 0.34 - DSC



Outlet



Culvert Floor



Inlet



Approach from Left Bank when facing downstream



SC-8217
SC-8217

THEODOSIA 9.1km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



SC-8217
SC-8217

THEODOSIA 9.1km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



SC-8217
SC-8217

THEODOSIA 9.1km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



SC-8217
SC-8217

THEODOSIA 9.1km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



SC-8217
SC-8217

THEODOSIA 9.1km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC

