

SC-8313
SC-8313

TEXADA BOB'S LAKE 0.3km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



CBR Data

Latitude	Longitude
49°36'8.2"	-124°17'29.6"
Crossing Name	Bob's Lake outlet
FSR #	5829
Branch #	06
Road Name	TEXADA BOB'S LAKE
User km	0.3
Previous Load Rating (tonnes)	136
Structure Class	Major Culvert
Culvert Type	Elliptical
Culvert Material	Corrugated Steel
Opening Height (mm)	1400
Opening Width (mm)	2130
Inlet Cover (mm)	500
Outlet Cover (mm)	500
Culvert Gradient %	
Culvert Length (m)	11.5

Updated Data

Latitude	Longitude
°0'0"	°0'0"
HD Diff. (m)	5521700.3
Accuracy (m)	
600	
700	

Inspection

Date of Inspection 2021-05-20 12:13:39 PM

Inspector Name Richard Mills


Inspector Comments

Recommended Next Inspection Year 2024

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. June 3, 2021
Load Rating: L150 or 136 tonnes
Next Inspection: 2024



P.Eng Seal

SC-8313
SC-8313

TEXADA BOB'S LAKE 0.3km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Approach

Alignment Good

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Unrated Na

Posted Load Rating

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall N/A

Bracing

Hardware

Fill Good

Riprap Good

Bearings

Corrosion Protection

SC-8313
SC-8313

TEXADA BOB'S LAKE 0.3km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Culvert

Baffles	Good
Bolted Connections	N/A
Coating	Good
Coupled Connections	Good
Embedment Materials	Good
Fill	Good
Floor	Good
Footing	Good
Head Walls	N/A
Inlet	Good
Outlet	Good
Overall	Good
Rip Rap	Good
Roof	Good
Sidewalls	Good
Trash Rack	N/A
Weirs/Backwater Structures	N/A
Wing Walls	N/A

SC-8313
SC-8313

TEXADA BOB'S LAKE 0.3km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SC-8313
SC-8313

TEXADA BOB'S LAKE 0.3km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Hazards

Estimated Present Water Level Depth (m) 0.1

High Water ☐

Debris ☐

Estimated Present Water Level Width (m) 0.5

Aggradation ☐

Scour ☐

Estimated High Water Level Clearance (m) 1.2

Ice ☐

Comments

Repairs and Monitoring

Repair Item Repair Description

1

2

3

4

5

6

7

Item

Monitor Description

Frequency

1

2

3

SC-8313
SC-8313

TEXADA BOB'S LAKE 0.3km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Approach from Right Bank when facing downstream



Outlet



Inlet



Outlet

SC-8313
SC-8313

TEXADA BOB'S LAKE 0.3km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



SC-8313
SC-8313

TEXADA BOB'S LAKE 0.3km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



SC-8313
SC-8313

TEXADA BOB'S LAKE 0.3km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



SC-8313
SC-8313

TEXADA BOB'S LAKE 0.3km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



SC-8313
SC-8313

TEXADA BOB'S LAKE 0.3km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC

