

SC-8333
SC-8333

HALLOWELL 0.72km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



CBR Data

Latitude	Longitude
49°38'43.5"	-123°57'24.7"
Crossing Name	Not Known
FSR #	8357
Branch #	02
Road Name	HALLOWELL
User km	0.72
Previous Load Rating (tonnes)	150
Structure Class	Temporary Bridge
Portable	N
Superstructure	Steel Box Beam
Deck Type	Gravel
Abutment Left	Concrete Lock Blocks
Abutment Right	Concrete Lock Blocks
Spans	1
Total Length (m)	8.9
Deck Width (m)	6

Updated Data

Latitude	Longitude
°0'0"	°0'0"
HD Diff. (m)	5526502.5
Accuracy (m)	

Inspection

Date of Inspection 2021-09-28 8:24:03 AM

Inspector Name Richard Mills

Inspector Comments Serial/ID Plate

Recommended Next Inspection Year 2023

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Nov 19, 2021
Load Rating: L165 or 150 tonnes
Next Inspection: 2023



P.Eng Seal

SC-8333
SC-8333

HALLOWELL 0.72km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Approach

Alignment Good

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Unrated N/a

Posted Load Rating

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete Good

Caps or Sills Fair

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware Good

Fill Good

Riprap Fair

Bearings Good

Corrosion Protection

SC-8333
SC-8333

HALLOWELL 0.72km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Deck

Running Surface **Good**

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints **N/A**

Steel Deck Plate

Gravel Surface **Good**

Curb Rail/Blocks/Posts **Good**

Hand Rails/Walkouts

Hardware **Good**

Overall Deck Condition **Good**

Gravel Depth (mm)

Pier Deck

SC-8333
SC-8333

HALLOWELL 0.72km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Steel/Concrete

Girders Good

Diaphragms N/A

Bracing N/A

Under Trussing

Hardware Good

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SC-8333
SC-8333

HALLOWELL 0.72km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Hazards

Estimated Present Water Level Depth (m)

High Water

☐

Debris

☐

Estimated Present Water Level Width (m)

Aggradation

☐

Scour

☒

Estimated High Water Level Clearance (m)

Ice

☐

Comments

Repairs and Monitoring

Repair Item

Repair Description

1

2

3

4

5

6

7

Item

Monitor Description

Frequency

1 Monitor riprap

Routine Inspection

2 Monitor sills

Routine Inspection


3

SC-8333
SC-8333

HALLOWELL 0.72km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



Structure ID



Left Bank Abutment when facing downstream

SC-8333
SC-8333

HALLOWELL 0.72km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Right Bank Abutment when facing downstream

SC-8333
SC-8333

HALLOWELL 0.72km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



SC-8333
SC-8333

HALLOWELL 0.72km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



SC-8333
SC-8333

HALLOWELL 0.72km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



SC-8333
SC-8333

HALLOWELL 0.72km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC

