

SC-8613
SC-8613

FLUME 0.6km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



CBR Data

Latitude 49°26'34.9" Longitude -123°36'25.8"

Crossing Name Unknown

FSR # 8546 Branch # 01

Road Name FLUME

User km 0.6

Previous Load Rating (tonnes) 0

Structure Class Woodbox/Log Culvert

Portable N

Superstructure

Deck Type

Abutment Left

Abutment Right

Spans 0

Total Length (m) 5

Deck Width (m)

Updated Data

Latitude °0'0" Longitude °0'0"

HD Diff. (m) 5503972.7 Accuracy (m)

Inspection

Date of Inspection 2021-09-28 11:42:16 AM

Recommended Next Inspection Year 2022

Inspector Name Richard Mills

Inspection Company FLNRORD

Inspector Comments Serial/ID Plate

This bridge appears to be behind large berm at start of road. Confirm it has been deactivated

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Nov 19, 2021
Load Rating: 0 tonnes
Next Inspection: 2022
Comments: Confirm structure has been deactivated and access blocked.



P.Eng Seal

SC-8613
SC-8613

FLUME 0.6km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Approach

Alignment

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☐ 2

Brushing Required

Delineator Missing
Left ☐ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☐ 0 ☐ 1 ☐ 2

Fender Condition

Posted Load Rating

Road Surface

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill

Riprap

Bearings

Corrosion Protection

SC-8613
SC-8613

FLUME 0.6km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Deck

Running Surface

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts

Hand Rails/Walkouts

Hardware

Overall Deck Condition

Gravel Depth (mm)

Pier Deck

SC-8613
SC-8613

FLUME 0.6km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Steel/Concrete

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SC-8613
SC-8613

FLUME 0.6km

2021 Inspection

CBR iPad Offline Ver 0.34 - DSC



Hazards

Estimated Present Water Level Depth (m)

High Water ☐

Debris ☐

Estimated Present Water Level Width (m)

Aggradation ☐

Scour ☐

Estimated High Water Level Clearance (m)

Ice ☐

Comments

Repairs and Monitoring

Repair Item

Repair Description

1

2

3

4

5

6

7

Item

Monitor Description

Frequency

1

2

3