

SC-8043
SC-8043

HOMATHKO 3.3km

2022 Inspection

CBR iPad Offline Ver



CBR Data

Latitude 50°56'9.89" Longitude -124°52'41.1"

Site Status Active

Insp. Status Inspect

Crossing Name Cumsack Slough

FSR # 7445 Branch # 1

Road Name HOMATHKO

User km 3.3

Previous Load Rating (tonnes) 136

Structure Class Permanent Bridge

Portable N

Superstructure Steel I-beam

Deck Type Timber - Treated

Abutment Left Other

Abutment Right Other

Spans 1

Total Length (m) 42.4

Deck Width (m) 4.88

Updated Data

Latitude 50°56'9.54" Longitude -124°52'40.75"

HD Diff. (m) 13.2 Accuracy (m) 5

Inspection

Date of Inspection 2022-09-27 8:37 AM

Recommended Next Inspection 2025

Inspector Name Jonathon Harvey

Inspection Company MoF

Inspector Comments Serial/ID Plate

Down rate until guardrails have been replaced. Post load rating signs.

P.Eng Comments

Load Rated by: MoF, J. Harvey P.Eng., November 2022

Load Rating: 0 Tonnes GVW

Next Inspection Year: 2025

Comments:



SC-8043
SC-8043

HOMATHKO 3.3km

2022 Inspection

CBR iPad Offline Ver



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required Y Brushy

Delineator Missing
Left ☐ 0 ☐ 1 ☒ 2

Delineator Missing
Right ☐ 0 ☐ 1 ☒ 2

Fender Condition Fair Logs

Posted Load Rating

Road Surface Fair

Abutment

Log/Timber Cribs N/A

Tie Backs N/A

Bin Wall N/A

Pier N/A

Concrete N/A

Caps or Sills Fair

Piles or Posts Fair

Ballast Wall Fair Large cedar logs

Wing Wall N/A

Bracing Fair

Hardware Fair

Fill Fair

Riprap Fair Minimal

Bearings Fair

Corrosion Protection Fair

SC-8043
SC-8043

HOMATHKO 3.3km

2022 Inspection

CBR iPad Offline Ver



Deck

Running Surface	Poor	
Running Planks	Poor	Rotten
Sub Deck	Fair	Creosote
Ties	Fair	Creosote
Nails	Fair	
Deck to Girder Bolts	Fair	
Concrete Deck	N/A	
Grout Pockets	N/A	
Deck Joints	N/A	
Steel Deck Plate	N/A	
Gravel Surface	N/A	
Curb Rail/Blocks/Posts	Poor	Rotten and falling off
Hand Rails/Walkouts	N/A	
Hardware	Fair	
Overall Deck Condition	Poor	Replace
Gravel Depth (mm)		
Pier Deck	N/A	

SC-8043
SC-8043

HOMATHKO 3.3km

2022 Inspection

CBR iPad Offline Ver



Steel/Concrete

Girders Fair Very minimal corrosion

Diaphragms Fair

Bracing Fair

Under Trussing N/A

Hardware Fair

Welded/grouted shear connectors N/A

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SC-8043
SC-8043

HOMATHKO 3.3km

2022 Inspection

CBR iPad Offline Ver



Hazards

Estimated Present Water Level Depth (m)	3	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	30	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance	1.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Approach. Area/sight line brushing. 20 m ² . Priority:Low	Brush sight lines when active
2 Structure. Full Curb Replacement. 80 . Priority:High	Replace guardrails
3 Structure. Minor redecking (wearing surface). 200 m. Priority:Medium	Replace wear deck
4 Approach. Add Warning Signs. 4 # of signs. Priority:Low	Add delineators

5

6

7


Item	Monitor Description	Frequency
1		
2		
3		



Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



Deck



Guard Rail



2022 Inspection

CBR iPad Offline Ver

HOMATHKO 3.3km

SC-8043
SC-8043



Upstream from Crossing



Downstream from Crossing



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream



2022 Inspection

CBR iPad Offline Ver

HOMATHKO 3.3km

SC-8043
SC-8043



Superstructure



Left Bank Abutment when facing downstream



Upstream Profile



Deck



Guard Rail



Downstream Profile



Right Bank Abutment when facing downstream