

SC-8077
SC-8077

MISERY CREEK 8.2km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°42'54.1" Longitude -123°37'16.6"

Site Status Active

Insp. Status Inspect

Crossing Name Not Known

FSR # 7895 Branch # 4

Road Name MISERY CREEK

User km 8.2

Previous Load
Rating (tonnes) 136

Structure Class Permanent Bridge

Portable N

Superstructure Steel I-beam

Deck Type Concrete Composite

Abutment Left Steel Pipe and Precast Pad

Abutment Right Steel Pipe and Precast Pad

Spans 1

Total Length (m) 18.3

Deck Width (m) 4.88

Updated Data

Latitude °0'0" Longitude °0'0"

HD Diff. (m) 5534251.6 Accuracy (m)

Inspection

Date of Inspection 2022-09-28 12:47:51 PM

Inspector Name Richard Mills

Recommended Next Inspection 2025

Inspection Company MoF

Inspector Comments Serial/ID Plate

Rust scale in girders, near joints. No apparent change since last inspection.

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Jan 24, 2023
Load Rating: L150 or 136 tonnes
Next Inspection: 2025



SC-8077
SC-8077

MISERY CREEK 8.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment **Good**

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required **Y** **Very brushed in**

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition **Good**

Posted Load Rating

Road Surface **Poor** **Alderred in**

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete **Good**

Caps or Sills **Good**

Piles or Posts **Good**

Ballast Wall **Good**

Wing Wall

Bracing **Good**

Hardware

Fill **Good**

Riprap **Good**

Bearings **Good**

Corrosion Protection

SC-8077
SC-8077

MISERY CREEK 8.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Deck

Running Surface Poor Aldered in

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck Good

Grout Pockets Good

Deck Joints Good

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Good

Hand Rails/Walkouts

Hardware Good

Overall Deck Condition Fair

Gravel Depth (mm)

Pier Deck

SC-8077
SC-8077

MISERY CREEK 8.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Steel/Concrete

Girders Fair

Rust scale in girders, near joints. No apparent change since last inspection.

Diaphragms Good

Bracing Good

Under Trussing

Hardware Good

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SC-8077
SC-8077

MISERY CREEK 8.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	0.4	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	3.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance	3.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
1	Monitor girder corrosion	Routine Inspection

2

3

SC-8077
SC-8077

MISERY CREEK 8.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Upstream Profile



Approach from Left Bank when facing downstream



Left Bank Abutment when facing downstream



Approach from Right Bank when facing downstream



SC-8077
SC-8077

MISERY CREEK 8.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Downstream Profile



Rust scale ds right abutment. Inside ds girder. Typical.



Structure ID



Downstream Profile

SC-8077
SC-8077

MISERY CREEK 8.2km

2022 Inspection

CBR iPad Offline Ver 0.36



Upstream Profile

