

SC-8142
SC-8142

SECHELT DAKOTA 27.1km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°30'33.9" Longitude -123°39'41.6"

Site Status Active

Insp. Status Inspect

Crossing Name Not known

FSR # 7575 Branch # 1

Road Name SECHELT DAKOTA

User km 27.1

Previous Load Rating (tonnes) 5

Structure Class Temporary Bridge

Portable N

Superstructure Steel I-beam

Deck Type Timber - Treated

Abutment Left Pile -Permanent Materials

Abutment Right Pile -Permanent Materials

Spans 1

Total Length (m) 10.7

Deck Width (m) 4.88

Updated Data

Latitude °0'0" Longitude °0'0"

HD Diff. (m) 5511363.1 Accuracy (m)

Inspection

Date of Inspection 2022-09-29 11:26:13 AM

Recommended Next Inspection 2023

Inspector Name Richard Mills

Inspection Company MoF

Inspector Comments Serial/ID Plate

Bridge condemned. Behind gate, deactivated road. Deck and ties rotted. Guardrails rotten. Replace all timber deck components for light vehicle access, replace entire structure if needed for industrial use.

Should be removed and blocked If accessible to vehicles.

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Jan 11, 2023

Load Rating: 0 tonnes

Next Inspection: 2023

Comments: Ensure access is blocked. Replace all timber deck components for light vehicle access, replace entire structure if needed for industrial use.



PERMIT TO PRACTICE: 1003022

SC-8142
SC-8142

SECHELT DAKOTA 27.1km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment Good

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition

Posted Load Rating 0 Condemned

Road Surface Poor Partial deactivated, gated. 4x4 atv only.

Abutment

Log/Timber Cribs Fair Fill retention only

Tie Backs Fair Fill retention only

Bin Wall

Pier

Concrete

Caps or Sills Good

Piles or Posts Good

Ballast Wall

Wing Wall

Bracing Good

Hardware Good

Fill Good

Riprap N/A

Bearings Good

Corrosion Protection Fair

SC-8142
SC-8142

SECHELT DAKOTA 27.1km

2022 Inspection

CBR iPad Offline Ver 0.36



Deck

Running Surface Poor Partial deactivated, gated. 4x4 atv only.

Running Planks Poor Rotten

Sub Deck Poor Rotten

Ties Poor Rotten

Nails Poor Loose

Deck to Girder Bolts Unrated Unable to see

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Poor Rotten

Hand Rails/Walkouts

Hardware Poor Loose

Overall Deck Condition Poor Rotten

Gravel Depth (mm)

Pier Deck

SC-8142
SC-8142

SECHELT DAKOTA 27.1km

2022 Inspection

CBR iPad Offline Ver 0.36



Steel/Concrete

Girders Fair

Old riveted steel i beams.

Diaphragms Good

Bracing Good

Under Trussing

Hardware Good

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SC-8142
SC-8142

SECHELT DAKOTA 27.1km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance	4	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
1 Structure. Full Curb Replacement. . Priority:High	Guardrails loose, rotten.
2 Structure. Timber deck maintenance. # of signs. Priority:High	Replace deck, ties. Currently inaccessible to vehicle)
3	
4	
5	
6	
7	

Item	Monitor Description	Frequency
1		
2		
3		

SC-8142
SC-8142

SECHELT DAKOTA 27.1km

2022 Inspection

CBR iPad Offline Ver 0.36



Superstructure



Left Bank Abutment when facing downstream



Approach from Left Bank when facing downstream



Right Bank Abutment when facing downstream



SC-8142
SC-8142

SECHELT DAKOTA 27.1km

2022 Inspection

CBR iPad Offline Ver 0.36



Load Rating Sign



Deck



Guard Rail



SC-8142
SC-8142

SECHELT DAKOTA 27.1km

2022 Inspection

CBR iPad Offline Ver 0.36



SC-8142
SC-8142

SECHELT DAKOTA 27.1km

2022 Inspection

CBR iPad Offline Ver 0.36



SC-8142
SC-8142

SECHELT DAKOTA 27.1km

2022 Inspection

CBR iPad Offline Ver 0.36



SC-8142
SC-8142

SECHELT DAKOTA 27.1km

2022 Inspection

CBR iPad Offline Ver 0.36

