

SC-8206
SC-8206

THEODOSIA 2.5km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°56'8"
Longitude -124°37'0"

Site Status Active

Insp. Status Inspect

Crossing Name Not Known

FSR # 6423 Branch # 10

Road Name THEODOSIA

User km 2.5

Previous Load
Rating (tonnes) 68

Structure Class Major Culvert

Culvert Type Elliptical

Culvert Material Corrugated Steel

Opening Height (mm) 2690

Opening Width (mm) 3890

Inlet Cover (mm) 950

Outlet Cover (mm) 1000

Culvert Gradient %

Culvert Length (m) 15.3

Updated Data

Latitude °0'0"
Longitude °0'0"

HD Diff. (m) 5558800.7 Accuracy (m)

800

1000

Inspection

Date of Inspection 2022-11-07 3:57:24 PM

Inspector Name Richard Mills

Inspector Comments

Large pipe. Check fill requirements

Recommended Next Inspection 2025

Inspection Company MoF

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Jan 19, 2023

Load Rating: L75 or 68 tonnes

Next Inspection: 2025



PERMIT TO
PRACTICE: 1003022

SC-8206
SC-8206

THEODOSIA 2.5km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment **Good**

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required **N**

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition

Posted Load Rating

Road Surface **Good**

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill **Good**

Riprap **Good**

Bearings

Corrosion Protection

SC-8206
SC-8206

THEODOSIA 2.5km

2022 Inspection

CBR iPad Offline Ver 0.36



Culvert

Baffles

Bolted Connections Good

Coating Fair Floor starting to show scaling

Coupled Connections

Embedment Materials

Fill Good

Floor Fair

Footing Good

Head Walls Good

Inlet Good

Outlet Good

Overall Good

Rip Rap Good

Roof Good

Sidewalls

Trash Rack

Weirs/Backwater
Structures

Wing Walls

SC-8206
SC-8206

THEODOSIA 2.5km

2022 Inspection

CBR iPad Offline Ver 0.36



Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SC-8206
SC-8206

THEODOSIA 2.5km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	2.0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance	2.0	Ic	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

SC-8206
SC-8206

THEODOSIA 2.5km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach from Left Bank when facing downstream



Outlet



Inlet



Superstructure

SC-8206
SC-8206

THEODOSIA 2.5km

2022 Inspection

CBR iPad Offline Ver 0.36



Inlet



Outlet



Culvert Floor

