

SC-8208
SC-8208-2

THEODOSIA 3.3km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°58'33.89" Longitude -124°38'58.1"

Site Status Active

Insp. Status Inspect

Crossing Name Not Known

FSR # 6423 Branch # 7

Road Name THEODOSIA

User km 3.3

Previous Load Rating (tonnes) 150

Structure Class Major Culvert

Culvert Type Round

Culvert Material Corrugated Steel

Opening Height (mm) 2400

Opening Width (mm) 2400

Inlet Cover (mm) 1000

Outlet Cover (mm) 2000

Culvert Gradient % 15

Culvert Length (m) 18

Updated Data

Latitude °0'0" Longitude °0'0"

HD Diff. (m) 5563312.1 Accuracy (m)

Inspection

Date of Inspection 2022-11-07 1:54:32 PM

Inspector Name Richard Mills

Recommended Next Inspection 2025

Inspection Company MoF

Inspector Comments

Trash rack old logs. Approx 20mm sap rot. Likely ineffective. No sign of debris movement. Stream doesn't appear to have high flows. Likely not needed

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Jan 18, 2023
Load Rating: L165 or 150 tonnes
Next Inspection: 2025
Comments: Monitor inlet



SC-8208
SC-8208-2

THEODOSIA 3.3km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Unrated N/a

Posted Load Rating

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall N/A

Bracing

Hardware

Fill Good

Riprap Good

Bearings

Corrosion Protection

SC-8208
SC-8208-2

THEODOSIA 3.3km

2022 Inspection

CBR iPad Offline Ver 0.36



Culvert

Baffles N/A

Bolted Connections N/A

Coating Fair Worn on bottom

Coupled Connections Good

Embedment Materials N/A

Fill Good

Floor Fair

Footing Good

Head Walls N/A

Inlet Good

Outlet Good

Overall Good

Rip Rap Good

Roof Good

Sidewalls Good

Trash Rack Poor Logs, approx. 20mm sap rot.

Weirs/Backwater Structures N/A

Wing Walls N/A

SC-8208
SC-8208-2

THEODOSIA 3.3km

2022 Inspection

CBR iPad Offline Ver 0.36



Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SC-8208
SC-8208-2

THEODOSIA 3.3km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)

High Water ☐

Debris ☐

Estimated Present Water Level Width (m)

Aggradation ☐

Scour ☐

Estimated High Water Level Clearance

Ic ☐

Comments

Repairs and Monitoring

Repair Item

Repair Description

1

2

3

4

5

6

7

Item

Monitor Description

Frequency

1

2

3

SC-8208
SC-8208-2

THEODOSIA 3.3km

2022 Inspection

CBR iPad Offline Ver 0.36



Inlet



Approach from Left Bank when facing downstream



Bush side culvert



Log trask rack. Rotten logs



SC-8208
SC-8208-2

THEODOSIA 3.3km

2022 Inspection

CBR iPad Offline Ver 0.36



Upstream from Crossing



Town side culvert



Town side culvert

