

SC-8216
SC-8216

THEODOSIA 7.11km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°59'31.3"
Longitude -124°40'54"

Site Status Active

Insp. Status Inspect

Crossing Name Not Known

FSR # 6423 Branch # 2

Road Name THEODOSIA

User km 7.11

Previous Load
Rating (tonnes) 91

Structure Class Major Culvert

Culvert Type Elliptical

Culvert Material Corrugated Steel

Opening Height (mm) 2080

Opening Width (mm) 2690

Inlet Cover (mm) 600

Outlet Cover (mm) 600

Culvert Gradient %

Culvert Length (m) 15

Updated Data

Latitude °0'0"
Longitude °0'0"

HD Diff. (m) 5565087.1 Accuracy (m)

Inspection

Date of Inspection 2022-11-07 2:41:11 PM

Inspector Name Richard Mills

Inspector Comments

Recommended Next Inspection 2025

Inspection Company MoF

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Jan 18, 2023
Load Rating: L100 or 91 tonnes
Next Inspection: 2025



PERMIT TO PRACTICE: 1003022

SC-8216
SC-8216

THEODOSIA 7.11km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment **Good**

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required **N**

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition

Posted Load Rating

Road Surface **Good**

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill **Good**

Riprap **Good**

Bearings

Corrosion Protection

SC-8216
SC-8216

THEODOSIA 7.11km

2022 Inspection

CBR iPad Offline Ver 0.36



Culvert

Baffles

Bolted Connections Good

Coating Fair

Coupled Connections

Embedment Materials

Fill Good

Floor Fair Corrosion, starting to scale

Footing Good

Head Walls

Inlet Good

Outlet Good

Overall Good

Rip Rap Good

Roof Good

Sidewalls

Trash Rack

Weirs/Backwater
Structures

Wing Walls

SC-8216
SC-8216

THEODOSIA 7.11km

2022 Inspection

CBR iPad Offline Ver 0.36



Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SC-8216
SC-8216

THEODOSIA 7.11km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	0.2	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance	2.0	Ic	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
1	Monitor culvert floor for corrosion	Routine Inspection

2

3

SC-8216
SC-8216

THEODOSIA 7.11km

2022 Inspection

CBR iPad Offline Ver 0.36



Culvert Floor



Inlet



Outlet

