

SC-8227
SC-8227

THEODOSIA 1km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



CBR Data

Latitude	Longitude
49°59'46.29"	-124°37'53.4"
Crossing Name	Not Known
FSR #	6423
Branch #	03
Road Name	THEODOSIA
User km	1
Previous Load Rating (tonnes)	150
Structure Class	Permanent Bridge
Portable	N
Superstructure	Concrete Slab Girders
Deck Type	Concrete
Abutment Left	Concrete Lock Blocks
Abutment Right	Concrete Lock Blocks
Spans	1
Total Length (m)	10.7
Deck Width (m)	4.8

Updated Data

Latitude	Longitude
°0'0"	°0'0"
HD Diff. (m)	5565550.9
Accuracy (m)	

Inspection

Date of Inspection 2022-09-26 2:46:07 PM

Inspector Name Richard Mills

Inspector Comments Serial/ID Plate

Recommended Next Inspection Year 2025


Inspection Company FLNRORD

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Jan 12, 2023

Load Rating: L165 or 150 tonnes

Next Inspection: 2025



P.Eng Seal

SC-8227
SC-8227

THEODOSIA 1km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Approach

Alignment Good

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete Fair Upstream right lock block spalling. All others ok

Caps or Sills Fair

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware Good

Fill Good

Riprap Good

Bearings Good

Corrosion Protection

SC-8227
SC-8227

THEODOSIA 1km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Deck

Running Surface Fair

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface Fair

Curb Rail/Blocks/Posts Fair

Hand Rails/Walkouts

Hardware Good

Overall Deck Condition Fair

Gravel Depth (mm)

Pier Deck

SC-8227
SC-8227

THEODOSIA 1km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Steel/Concrete

Girders **Good**

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors

Unrated

Unable to see

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SC-8227
SC-8227

THEODOSIA 1km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Hazards

Estimated Present Water Level Depth (m)	0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	1.2	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
1	Monitor upstream right side lock block	Routine Inspection

2

3

SC-8227
SC-8227

THEODOSIA 1km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Right Bank Abutment when facing downstream



Upstream right lock block



Approach from Left Bank when facing downstream



Left Bank Abutment when facing downstream

