

SC-8229
SC-8229

THEODOSIA 1.3km

2022 Inspection

CBR iPad Offline Ver 0.36



CBR Data

Latitude 49°56'21.99"
Longitude -124°38'58"

Site Status Active

Insp. Status Inspect

Crossing Name Not Known

FSR # 6423 Branch # 2

Road Name THEODOSIA

User km 1.3

Previous Load
Rating (tonnes) 68

Structure Class Permanent Bridge

Portable N

Superstructure Concrete Slab Girders

Deck Type Gravel

Abutment Left Steel Pipe and Precast Pad

Abutment Right Steel Pipe and Precast Pad

Spans 1

Total Length (m) 7.8

Deck Width (m) 5.5

Updated Data

Latitude °0'0"
Longitude °0'0"

HD Diff. (m) 5559233.5 Accuracy (m)

Inspection

Date of Inspection 2022-11-07 3:34:53 PM

Inspector Name Richard Mills

Recommended Next Inspection 2025

Inspection Company MoF

Inspector Comments Serial/ID Plate

Beaver dam at inlet. No apparent change since last inspection. Replace guardrails.

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Jan 19, 2023
Load Rating: 75 or 68 tonnes
Next Inspection: 2025
Comments: Replace guardrails.



PERMIT TO
PRACTICE: 1003022

SC-8229
SC-8229

THEODOSIA 1.3km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☒ 2

Brushing Required N

Delineator Missing
Left ☐ 0 ☒ 1 ☐ 2

Delineator Missing
Right ☐ 0 ☒ 1 ☐ 2

Fender Condition Good

Posted Load Rating

Road Surface Good

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete Good

Caps or Sills Good

Piles or Posts Good

Ballast Wall Good

Wing Wall

Bracing

Hardware Good

Fill Good

Riprap Fair

Bearings Good

Corrosion Protection Fair

SC-8229
SC-8229

THEODOSIA 1.3km

2022 Inspection

CBR iPad Offline Ver 0.36



Deck

Running Surface **Good**

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck **Good**

Grout Pockets

Deck Joints **Good**

Steel Deck Plate

Gravel Surface **Good**

Curb Rail/Blocks/Posts **Poor** Loose, rotten. Replace.

Hand Rails/Walkouts

Hardware **Good**

Overall Deck Condition **Good**

Gravel Depth (mm)

Pier Deck

SC-8229
SC-8229

THEODOSIA 1.3km

2022 Inspection

CBR iPad Offline Ver 0.36



Steel/Concrete

Girders Good

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted shear connectors Unrated Unable to see

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SC-8229
SC-8229

THEODOSIA 1.3km

2022 Inspection

CBR iPad Offline Ver 0.36



Hazards

Estimated Present Water Level Depth (m)	0.2	High Water	☒	Debris	☒
Estimated Present Water Level Width (m)	2.0	Aggradation	☐	Scour	☒
Estimated High Water Level Clearance	1.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1	Structure. Full Curb Replacement. . Priority:High
---	---

2

3

4

5

6

7

Item	Monitor Description	Frequency
------	---------------------	-----------

1	Monitor inlet / beaver dam	
---	----------------------------	--

2

3

SC-8229
SC-8229

THEODOSIA 1.3km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach from Right Bank when facing downstream



Guard Rail



Right Bank Abutment when facing downstream



Left Bank Abutment when facing downstream

SC-8229
SC-8229

THEODOSIA 1.3km

2022 Inspection

CBR iPad Offline Ver 0.36



Inlet

