

SC-8233  
SC-8233

## THEODOSIA 3.5km

2022 Inspection

CBR iPad Offline Ver 0.36



### CBR Data

Latitude 49°57'19.69"  
Longitude -124°39'33.1"

Site Status Active

Insp. Status Inspect

Crossing Name Not known

FSR # 6423 Branch # 2

Road Name THEODOSIA

User km 3.5

Previous Load  
Rating (tonnes) 68

Structure Class Permanent Bridge

Portable N

Superstructure Concrete Slab Girders

Deck Type Gravel

Abutment Left Concrete Lock Blocks

Abutment Right Concrete Lock Blocks

Spans 1

Total Length (m) 6.5

Deck Width (m) 8.8

### Updated Data

Latitude °0'0"  
Longitude °0'0"

HD Diff. (m) 5561017.7 Accuracy (m)

### Inspection

Date of Inspection 2022-11-07 3:13:26 PM

Inspector Name Richard Mills

Inspector Comments Serial/ID Plate

Recommended Next Inspection 2025

Inspection Company MoF

### P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Jan 19, 2023  
Load Rating: 75 or 68 tonnes  
Next Inspection: 2025



PERMIT TO  
PRACTICE: 1003022

SC-8233  
SC-8233

THEODOSIA 3.5km

2022 Inspection

CBR iPad Offline Ver 0.36



## Approach

Alignment Fair

Bridge Ahead Signs  
Missing ☐ 0 ☒ 1 ☐ 2

Brushing Required N

Delineator Missing  
Left ☐ 0 ☐ 1 ☒ 2

Delineator Missing  
Right ☐ 0 ☒ 1 ☐ 2

Fender Condition Good

Posted Load Rating

Road Surface Good

## Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete Good

Caps or Sills Good

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware Good

Fill Good

Riprap Good

Bearings Good

Corrosion Protection

SC-8233  
SC-8233

THEODOSIA 3.5km

2022 Inspection

CBR iPad Offline Ver 0.36



## Deck

Running Surface      Fair

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck      Good

Grout Pockets

Deck Joints      Good

Steel Deck Plate

Gravel Surface      Fair

Curb Rail/Blocks/Posts      Good

Hand Rails/Walkouts

Hardware      Good

Overall Deck Condition      Good

Gravel Depth (mm)

Pier Deck

SC-8233  
SC-8233

THEODOSIA 3.5km

2022 Inspection

CBR iPad Offline Ver 0.36



## Steel/Concrete

Girders Good

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted  
shear connectors

Unrated

Unable to see

## Log

Log Curbs

Needle Beam

Needle Lashing/  
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer  
Number

Species

Peeled

Diameter  
(mm)

Rot Depth  
(mm)

Condition

Comment

SC-8233  
SC-8233

THEODOSIA 3.5km

2022 Inspection

CBR iPad Offline Ver 0.36



## Hazards

|                                         |     |             |                          |        |                          |
|-----------------------------------------|-----|-------------|--------------------------|--------|--------------------------|
| Estimated Present Water Level Depth (m) | 0.2 | High Water  | <input type="checkbox"/> | Debris | <input type="checkbox"/> |
| Estimated Present Water Level Width (m) | 1.5 | Aggradation | <input type="checkbox"/> | Scour  | <input type="checkbox"/> |
| Estimated High Water Level Clearance    | 2.5 | Ice         | <input type="checkbox"/> |        |                          |

Comments

## Repairs and Monitoring

| Repair Item | Repair Description |
|-------------|--------------------|
|-------------|--------------------|

1

2

3

4

5

6

7

Item

Monitor Description

Frequency

1

2

3

SC-8233  
SC-8233

## THEODOSIA 3.5km

2022 Inspection

CBR iPad Offline Ver 0.36



Approach from Right Bank when facing downstream



Approach from Left Bank when facing downstream



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream