

SC-8237
SC-8237

THEODOSIA 11.9km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



CBR Data

Latitude 49°59'18.6" Longitude -124°36'42.5"

Crossing Name Appleton Creek

FSR # 6423 Branch # 01

Road Name THEODOSIA

User km 11.9

Previous Load Rating (tonnes) 150

Structure Class Permanent Bridge

Portable N

Superstructure Steel I-beam

Deck Type Concrete Composite

Abutment Left Steel Pipe and Precast Pad

Abutment Right Steel Pipe and Precast Pad

Spans 1

Total Length (m) 17.1

Deck Width (m) 4.88

Updated Data

Latitude °0'0" Longitude °0'0"

HD Diff. (m) 5564694.4 Accuracy (m)

Inspection

Date of Inspection 2022-09-26 2:02:36 PM

Recommended Next Inspection Year 2025

Inspector Name Richard Mills

Inspection Company FLNRORD

Inspector Comments Serial/ID Plate

Isolated corrosion on girder, at deck joints. Upstream right side, 1st joint is worst.

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Jan 23, 2023
Load Rating: L165 or 150 tonnes
Next Inspection: 2025



P.Eng Seal

SC-8237
SC-8237

THEODOSIA 11.9km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Approach

Alignment Good

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition Good

Posted Load Rating

Road Surface Fair

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete Good

Caps or Sills Good

Piles or Posts Good

Ballast Wall Good

Wing Wall

Bracing Good

Hardware Good

Fill Good

Riprap Good

Bearings Good

Corrosion Protection Good

SC-8237
SC-8237

THEODOSIA 11.9km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Deck

Running Surface

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts

Hand Rails/Walkouts

Hardware

Overall Deck Condition

Gravel Depth (mm)

Pier Deck

SC-8237
SC-8237

THEODOSIA 11.9km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Steel/Concrete

Girders Fair Isolated corrosion at deck joints.

Diaphragms Good

Bracing Good

Under Trussing

Hardware Good

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer
Number

Species

Peeled

Diameter
(mm)

Rot Depth
(mm)

Condition

Comment

SC-8237
SC-8237

THEODOSIA 11.9km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	1.2	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	2.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3

SC-8237
SC-8237

THEODOSIA 11.9km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Approach from Left Bank when facing downstream



Approach from Right Bank when facing downstream



Upstream Profile



Deck



SC-8237
SC-8237

THEODOSIA 11.9km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Left Bank Abutment when facing downstream



1st joint, upstream right



Downstream Profile



1st joint , upstream right, on inside



SC-8237
SC-8237

THEODOSIA 11.9km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Right Bank Abutment when facing downstream



1st joint, upstream right side



Downstream Profile



Upstream left side