

SC-8242
SC-8242

THEODOSIA 11.52km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



CBR Data

Latitude	Longitude
49°59'24.9"	-124°36'26.3"
Crossing Name	Junction Creek
FSR #	6423
Branch #	01
Road Name	THEODOSIA
User km	11.52
Previous Load Rating (tonnes)	150
Structure Class	Permanent Bridge
Portable	N
Superstructure	Steel I-beam
Deck Type	Concrete Composite
Abutment Left	Other
Abutment Right	Other
Spans	1
Total Length (m)	15.2
Deck Width (m)	4.88

Updated Data

Latitude	Longitude
°0'0"	°0'0"
HD Diff. (m)	5564889.2
Accuracy (m)	

Inspection

Date of Inspection 2022-09-26 1:46:20 PM

Inspector Name Richard Mills


Inspector Comments Serial/ID Plate

Recommended Next Inspection Year 2025

Inspection Company FLNRORD

P.Eng Comments

Load Rated by: Richard Mills, P.Eng. Jan 12, 2023
Load Rating: L165 or 150 tonnes
Next Inspection: 2025



P.Eng Seal

SC-8242
SC-8242

THEODOSIA 11.52km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Approach

Alignment Good

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required N

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition

Posted Load Rating

Road Surface

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete Good

Caps or Sills Good

Piles or Posts Good

Ballast Wall Good

Wing Wall

Bracing Good

Hardware Good

Fill Good

Riprap Good

Bearings Good

Corrosion Protection Good

SC-8242
SC-8242

THEODOSIA 11.52km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Deck

Running Surface Fair

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints Fair

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Fair Likely will require replacement in 3 years

Hand Rails/Walkouts

Hardware Good

Overall Deck Condition Fair

Gravel Depth (mm)

Pier Deck

SC-8242
SC-8242

THEODOSIA 11.52km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Steel/Concrete

Girders Good

Diaphragms Good

Bracing Good

Under Trussing

Hardware Good

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SC-8242
SC-8242

THEODOSIA 11.52km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	1.2	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance (m)	2.0	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2


3

SC-8242
SC-8242

THEODOSIA 11.52km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Approach from Right Bank when facing downstream



Right Bank Abutment when facing downstream



Approach from Left Bank when facing downstream



Left Bank Abutment when facing downstream

SC-8242
SC-8242

THEODOSIA 11.52km

2022 Inspection

CBR iPad Offline Ver 0.34 - DSC



Upstream Profile

